



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23003828/Any3q2 Date: 16/06/2023  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLJ 2500R	Veh. Inspected	SMN 1771Z
Policy No.	P10462814R02	Coverage (\$)	0.00
Claim No.	C10021570/JL	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	13/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MINI ONE	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WMWXU520002L02211	Colour	BRONZE
Odometer	23454 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/55 R16	HANKOOK	6 mm
L/H Front Tyre	195/55 R16	HANKOOK	6 mm
R/H Rear Tyre	195/55 R16	HANKOOK	6 mm
L/H Rear Tyre	195/55 R16	HANKOOK	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	08/04/2023	Inspection Date	17/04/2023
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	