ASS. FILE BY: REF:

# ASSIGNMENT

From : Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMN 1771 Z Yr Regn: 2019, July.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mini One c.c 1499

Colour Bronze. A/C: Insured / Std / NI / NA

Sp.Reading 23454 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMWXU520002L02211

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R16.

R: 195/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook.

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 06 mm | R/Bal. | 06 mm |
| L/Bal. | 06 mm | L/Bal. | 06 mm |
| D.O.A. | | D.O.I. | 17/02/23. |

Survey held at YSK.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | TP Budget Direct. |
| | |
| | |
| | MV : |
| | PV : |
| | Nett : |
| | |
| | 948J. |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LPR / 3

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ )

☐ : Interview ($ )

☐ : Tech. Inve ($ )

☐ : Workshop ($ )

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others