

ASS. REC. BY:

REF:

TJ / 23003834/kp
GRB

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

RS

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

854K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 4495A Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel c.c. 1498

Colour

M.D. Grey A/C: Insured / Std / NI / NA

Sp. Reading

178105 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU3 1211200

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3 mm

R/Bal.

6 mm

L/Bal.

3 mm

L/Bal.

6 mm

D.O.A.

3/4/23

D.O.A.

17/4/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/4 11:20 819506 Car Ins

Data/Time, File Pass to?



: Prell. Report

1)



: Final Report

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fixtures

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

RS AUTO SERVICES

160, SIN MING DRIVE

SIN MING AUTOCITY # 06-01

EMAIL : rsautoservices88@gmail.com H.P 93825367

Not Authorized

1/19/23 @ 1950hr

Resurvey After Rain

4 days

Survey Date : 17 Apr 2023

INDIA INTERNATIONAL INSURANCE

CLAIM : THIRD PARTY CLAIM

VEH. No : SLG 4495 A / VEZEL

ACCIDENT DATE : 1/4/2023

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
-----	------	--------	-----------

THIRD PARTY VEHICLE : SNB 9492 C

1	FRONT LH FENDER	REPAIR	
1	FRONT LH FENDER EMBLEM	\$ <i>mc</i> 65.00	—
1	FRONT LH DOOR <i>950</i>	\$ <i>By</i> 1,255.00	—
1	FRONT LH DOOR WINDOW GEAR <i>450</i>	\$ <i>Di</i> 480.00	✓
1	FRONT LH DOOR WEATHERSTRIP	\$ <i>pu</i> 280.00	X
1	FRONT LH DOOR INNER RUBBER	\$ <i>pu</i> 161.00	X
2	FRONT LH DOOR WINDOW FRAME TAPES	\$ <i>mc</i> 80.00	—
1	FRONT LH DOOR EDGE STAND RUBBER	\$ <i>nd</i> 120.00	✓
1	FRONT LH DOOR TRIM BOARD	\$ <i>mtj</i> <i>Chs</i> 480.00	X
1	FRONT LH DOOR PILLAR	REPAIR	
1	LH SIDE ROCKER PANEL GARNISH	\$ <i>mc</i> 980.00	X
1	LH SIDE ROCKER PANEL	REPAIR	
1	FRONT SIDE MIRROR MOTOR	\$ <i>pu</i> 480.00	X
1	FRONT SIDE MIRROR COVER	\$ <i>pu</i> 220.00	^
1	REAR LH DOOR	REPAIR	
1	REAR LH DOOR OUTER TRANSPARENT STICKER	\$ <i>pu</i> 55.00	X
TOTAL PARTS :		\$ 4,656.00	
LESS 20%		\$ 931.20	
TOTAL LIST PARTS :		\$ 3,724.80	
SPECIAL / NETT PARTS			
1SET	FRONT LH RIM	\$ <i>pu</i> 600.00	X
10	ROCKER PANEL GARNISH CLIPS LH	\$ <i>pu</i> 45.00	X
1SET	FRONT SIDE MIRROR OUTER COVER LH	\$ <i>pu</i> 300.00	X
TOTAL S/N PARTS :		\$ 945.00	
TOTAL PARTS PRICE :		\$ 4,669.80	

LABOUR CHARGES	AMOUNT	CONDITION
Labour charges to repair , replace accident affected area	\$ 800.00	400
To remove refix , replace garnish, Trim board, upholstery etc	\$ na 180.00	X
Transfer door parts to another door	\$ 120.00	600
Check door wiring system	\$ 120.00	200
To do anti rust	\$ 120.00	300
To do spray painting on accident affected area inner and outer	\$ 800.00	600
To do computer setting after repair	\$ na 180.00	X
TOTAL LABOUR :	\$ 2,320.00	
GRAND TOTAL PARTS & LABOUR :	\$ 6,989.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: