

08/13/13 WEL
ASS. REC. BY: [Signature]

REF:

CS3/SNR 2300384/Rvy 3

4192

COE - 2032/1/1/1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBG 5089B

at Workshop m/s HUA CHIN

of BUILT BAYOK ST 23

Insured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 13K

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBG 5089B Yr Regn: 2012 1 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA JUPITER MX (HC) cc 134

Colour Red A/C: Insured / Std / NI / NA

Sp. Reading 98047 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH35066029K385113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17

R: 90/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TIM SAN

Front

R/Bal. 4 mm

L/Bal. _____ mm

D.O.A. 31/03/23

Survey held at

HUA CHIN

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 3.5K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 419Z

Vehicle Details

Vehicle No.: FBG5089B

Vehicle to be Exported: No

Intended Deregistration Date: 18 Apr 2023

Vehicle Make: YAMAHA

Vehicle Model: JUPITER MX (HC)

Primary Colour: Red

Manufacturing Year: 2012

Engine No.: 50C385160

Chassis No.: MH350C002CK385113

Maximum Power Output:

Open Market Value: \$1,870.00

Original Registration Date: 13 Aug 2012

First Registration Date: 13 Aug 2012

Transfer Count: 2

Actual ARF Paid: \$281.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2032

COE Category: D - Motorcycle

COE Period(Years): 10

PQP Paid: \$10,180.00

COE Rebate Amount: \$9,484.00

Total Rebate Amount: \$9,484.00

Message