

(08/13) WEL

ASS. REC. BY: [Signature]

REF:

CS3/SNR 2300384/Rvy 3

4192

COE - 2032/1/100

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBG 5089B

at Workshop m/s

HUA CHIN

of

BUILT BAYOK ST 23

Insured:

SMB 3587P SML

Policy No.

Claims No.

BUS/03/23/5045

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

13K

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBG 5089B

Yr Regn:

2012 1 Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA JUPITER MX (HC) c.c 134

Colour

RED

A/C:

Insured / Std / NI / NA

Sp. Reading

98047

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH3 506 0029K 38 S/13

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

90/90-17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TIMSUN

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

31/03/23

D.O.I.

14/04/23

Survey held at

HUA CHIN

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 3.5K

18/4/23

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?



: Prel. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

1)

Date/Time, File Return to?

2) 18/4/23-typist

Report Format :

Lump Sum / I.B.I. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 419Z

Vehicle Details

Vehicle No.: FBG5089B

Vehicle to be Exported: No

Intended Deregistration Date: 18 Apr 2023

Vehicle Make: YAMAHA

Vehicle Model: JUPITER MX (HC)

Primary Colour: Red

Manufacturing Year: 2012

Engine No.: 50C385160

Chassis No.: MH350C002CK385113

Maximum Power Output:

Open Market Value: \$1,870.00

Original Registration Date: 13 Aug 2012

First Registration Date: 13 Aug 2012

Transfer Count: 2

Actual ARF Paid: \$281.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2032

COE Category: D - Motorcycle

COE Period(Years): 10

PQP Paid: \$10,180.00

COE Rebate Amount: \$9,484.00

Total Rebate Amount: \$9,484.00

Message