

ASS. REC. BY: Taught

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHE328N Yr Regn: 2022 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 81597 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STOKES3F4123096783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 24

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/4/23

Survey held at Comfort Way

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / LBR (F) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

_____\$ + RS. ____\$

Photos _____

Others _____

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC3328A
MAKE TOYOTA
MODEL PRIUS

DATE: 12.04.23
MVA JUMANI
DOA: 11.04.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$503.04
1	REAR BUMPER CENTRE MLDG			\$654.96
1	REAR BUMPER BEAM			\$378.33
10	REAR BUMPER CLIPS			\$22.00
SUB TOTAL				\$1,558.33
LESS 25%				\$389.58
DISCOUNTED TOTAL				\$1,168.75
Labour Charge				
PANEL BEATING –				\$400.00
SPRAY PAINT				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$50.00
TOTAL LABOUR				\$750.00
ESTIMATE TOTAL				\$1,918.75
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NET
NET
NET

350
250
30

Tanji 97495719
12/4/23 4pm
P/P Repair new parts
2 days
Tanji @ LK Auto

LKK Auto Consultants
We Repair the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Date/Time: 12.04.2023 13:37

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892793

JC NO305550993

OMER
3 COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO: SHC3328A	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A11.04.2023 17:00	DATE/TIME IN
YR OF MANU 06.07.2022	TARGET DATE
CHASSIS CODE JTDKB3FU103096783	COMPLETION DATE/TIME:

UNT CARD NO.

JOB DESCRIPTION

cident Date: 11.04.2023
TURE: 3P.11.04.23

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SHC3328A JU INCOME

Vehicle No.: SHC3328A

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard