SS2O234E0001 / SBS Transit Ltd[659519] ENTRY DATE & TIME: 14/04/2023 09:06 (SGT) SUBMITTED BY: Steven Lee Kok Leong VERSION: 1 (14/04/2023 09:06 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/04/2023 09:06 (SGT) Reported by Owner Date of Accident 07/04/2023 20:42 (SGT) Exact Location of Accident Dhoby Ghaut Stn Exit B, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBS8862C

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner SBS Transit Ltd Company Reg No 199206653MPTE01 Email Address leekokleong@sbstransit.com.sg Mobile Phone No (Phone) +65-00000000 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Scania Model KUB 4X2 Variant Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party

Vehicle Category Bus Transmission Auto CC 8867

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd Policy Number / Cover Note Number D-22099137MFBP

DRIVER

Name of Driver **WANG BIN** Work Permit No S7289966J Date Of Birth 21/09/1972 Occupation Outdoor

Date Of Driving Pass 03/10/2016 Driving experience 6 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-00000000 Alt. Phone Number Email Address leekokleong@sbstransit.com.sg Address 1 HOLLAND CLOSE #11-103 SINGAPORE Address complement Postcode 271001 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 28 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name **UNKNOWN** Gender Male PASSENGER 2 Name UNKNOWN Gender Male PASSENGER 3 Name **UNKNOWN** Gender Female PASSENGER 4 Name **UNKNOWN** Gender Female PASSENGER 5 Name **UNKNOWN** Gender Male PASSENGER 6 UNKNOWN Gender Male PASSENGER 7 UNKNOWN

Female

Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	_

CIRCUMSTANCES OF ACCIDENT

According to BC Wang Bin (82325) reported his bus was hit by GAS Svc36/SBS6455H/BC10203 head to rear at Dhoby Ghaut Station Exit B location.

Accident happened when SBS8862C was conducting pickup/alighting activities and the rear bus hit onto his bus. No injury reported on both buses.

After exchange particulars, BC was instructed RTD to BBD after consulted CRS.

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer	SBS6455H
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	GO AHEAD SINGAPORE - BC10203
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	HEAD TO REAR
Details of property damaged in accident	LHS DIED MIRROR DAMAGED
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s). who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date & Time

LEE KOK LEONG Operations Personnel **Bukit Batok Depet**

Witnessed by Reporting Centre Personnel

Sketch Plan

Time



R194

		I/O In charge	:	
SBSTre	ancit	Report No	:	48-2023-1988
ه ۱۱ و معاد		Date & Time Acc	:	7/4/23
		意外日期與時間	:	2042 HRS
01 1	731	Bus No: 巴士 車牌	.	885 58 62 C
Sketch	Plan	Svc No: 路線:		111
Oncicii	1 1411	BC No: 工牌機關		82825
		BC Name: 姓名:		NANG SIN
		Signature: 簽名:		× 王秋
		Date: 日期:	T	11/4/23
	S-STOP			