

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI23003944/Uvy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	15/05/2023	
			C	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMJ 3156H	Veh. Inspected		FBN 9708K	
	Policy No.	P10526758R02	Coverage (\$)		0.00	
	Claim No.	C10021316 /CH	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		17/04/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	SYM MAXSYM 400I	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	RFGLXA901JSA00378	Colour		GREY	
	Odometer	21780 KM	Steering		AFFECTED	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120-70-15	SHINKO		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160-60-14	SHINKO		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION & O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/03/2023	Inspection Date		19/04/2023	
	Survey held at	y held at EROFIA MOTOR TRADING PTE LTD				
		1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D. Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: