

Our J	ob Ref	No : 30	5545236		ENGINEERING			
Date : 14/02/23			4/02/23		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156			
FINA	LIZATI	ON FORM						
То	:		LKK			Fax:		
Attn			_ ***					
Vehic	le Reg	No. : SHA182	20T			_	06.02.2023	
The s	survey	and estimates of th	e repairs of the above	-mention	ed vehicle	are as follows:	-	
1.	The r	epair job shall bill t	o: <u>/</u>	INCOME		/ ** //	SLT1010S	
2.		nalized amount sh				Đ.		
70	(a)	Spare Parts after						
	(b)	Labour Charges					\$910.00	
	(2)		-Part Repair Cost				\$910.00	
		, , , , , , , , , , , , , , , , , , , ,						
	(c.)	Lumpsum Repair		20%				
		Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost			2070		\$0.00	
		Fertimated normal period for repairs: 2 working days.						
3.	Estimated normal period to repairs							
4.		hall treat the abo rking days	ve amount as Correc	t and Co	onfirmed if	there is no re	eply from you within	
5.	Thank you for your assistance.				We confirm the estimates and			
0.	11101	,	V	finalized amount				
			Λ					
				V	Signature:			
	_		0/		Name :			
	Nam	· · · · · · · · · · · · · · · · · · ·	<u>~</u>		Date :			
	Tel	Tel : 62148355						
	Fax	<u>65468156</u>						
For	Officia	I Use Only						
		Item	Amount		ocument Attached Yes or No	Confirm By (Signature)	Remarks	
1	Jantal I	Poto P/Day			YES			
_	Rental Rate P/Day Loss of Income Paid				NO			
3. Survey Fees								
	4. LTA Search Fee \$26							
Medical Fees (on behalf								
	of drive	r, if applicable)						
0	Overrui							
Ren	narks:							