Surveyor:

REF: CS3/CTI22010245/Tny3-1

Special Instruction:

LS: $6100 / 8 DAYS

ASSIGNMENT (Office)

From (Person): JACQUELINE TAN of CTI Date/Time: 14/04/2023

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: _____

Surveyor: CL APPRAISER

Workshop: ESL AUTOMOTIVE PTE LTD

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJS 3093T Insured: GBJ 4842J

at Workshop m/s ESL AUTOMOTIVE PTE LTD Tel: _____

of 25 KAKI BUKIT ROAD 4, #07-47/75, SYNERGY @ KB, SINGAPORE 417800

Policy No: DMCVSNW00050052203 Claim No: SNM22D207361/C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/10/2022

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle **IN / OUT**

Date/Time: _____ **Confirmed with** _____ **Final Fig** _____, ___**days (Red $**____/___**%; Original** 7 **days)**

Date/Time: 04/08/23 **Submit Final Fig** $4750, 6 **days (Red $** 1350/ 22 **%; Original** 8 **days)**

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____