



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile              |                                                                                                                                        |                                                                         |                           |            |
|--------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|---------------------------|------------|
| ETHOZ PROTECT PTE LTD<br>30 BUKIT BATOK CRESCENT SINGAPORE<br>SINGAPORE 658075 |                                                                                                                                        |                                                                         | Ref: CS/TP23003975/Uwy3e2 |            |
|                                                                                |                                                                                                                                        |                                                                         | Date: 12/05/2023          |            |
|                                                                                |                                                                                                                                        |                                                                         | Code: TP513               |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                              |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | Insured Veh.                                                                                                                           | JTG 8944                                                                | Veh. Inspected            | YP 2763M   |
|                                                                                | Policy No.                                                                                                                             |                                                                         | Coverage (\$)             | 0.00       |
|                                                                                | Claim No.                                                                                                                              |                                                                         | Excess (\$)               | 0.00       |
|                                                                                | Assign From                                                                                                                            |                                                                         | Assign Date               | 18/04/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                  |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | Make & Model                                                                                                                           | ISUZU FRR90                                                             | c.c                       | 5193       |
|                                                                                | Engine No.                                                                                                                             | 4HK1281996                                                              | Year of Reg.              | 2016       |
|                                                                                | Chassis No.                                                                                                                            | JALFRR907E7000442                                                       | Colour                    | WHITE      |
|                                                                                | Odometer                                                                                                                               | 263562 KM                                                               | Steering                  | IN ORDER   |
|                                                                                | Brakes                                                                                                                                 | IN ORDER                                                                | Modification              | NIL        |
|                                                                                | General                                                                                                                                | GOOD                                                                    |                           |            |
| <b>3. Conditions of Tyres</b>                                                  |                                                                                                                                        |                                                                         |                           |            |
|                                                                                |                                                                                                                                        | Size                                                                    | Make                      | Balance    |
|                                                                                | R/H Front Tyre                                                                                                                         | 9.5 R17.5                                                               | GITI                      | 6 mm       |
|                                                                                | L/H Front Tyre                                                                                                                         | 9.5 R17.5                                                               | GITI                      | 6 mm       |
|                                                                                | R/H Rear Tyre                                                                                                                          | 9.5 R17.5 (D)                                                           | GITI                      | 6/6 mm     |
|                                                                                | L/H Rear Tyre                                                                                                                          | 9.5 R17.5 (D)                                                           | GITI                      | 6/6 mm     |
| <b>4. Description of Damages</b>                                               |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                         |                           |            |
| <b>5. General Information</b>                                                  |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | Accident Date                                                                                                                          | 24/02/2023                                                              | Inspection Date           | 18/04/2023 |
|                                                                                | Survey held at                                                                                                                         | ETHOZ PROTECT PTE. LTD.<br>30 BUKIT BATOK CRESCENT,<br>SINGAPORE 658075 |                           |            |
| <b>5a. Remarks</b>                                                             |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                         |                           |            |
| <b>5b. Estimate Days of Repair</b>                                             |                                                                                                                                        |                                                                         |                           |            |
|                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                         | 3 Working Days            |            |