i bau, ;	KEF; CS/T	MI23003981/Sq	y3 '.	<u>j</u> *	
ASS, REC, BY;		ASSIGNMENT		:	
From: Estimated Cost ODITPIWSITPRESIOD RESIL	Date:	Type: M.Cu/M.	Cycle Bus Van Lorry aller or		798
et Workshop m/s	(m1	Sp.Reading \		Insured Isld Insured Isld Insured Isld	
Policy No. Cioles No. Sum Insured: (Ciloni's Record) Make of Vets	Excess:	Gan, Cond: Good Stearing: Inogder Brake: Inogder Modi: Nil / Si	d Fair Poor Burnt Jammod Leakid Bu Jammed Leakid Bu Rim SID A/Rim; or	rator j~	
(Policy Condition) Romaric The web had commenced repair at the time of Insp Bol or Markot Value: DAC Accident Roort GIA / PR Scen: Est. Repairs: Lum Sum: CA / REV / REP. / 24 HRS	consistent 7: Yes or No consistent 7: Yes or No Res: Yes or No 3 Val: Yes or No Vehicle:	BS/DUN/EXCH TOYO/YOKO Front RUBAL S D.O.A. 5 / 4 Survey hold at Des. of Damages	mm ·	REDE SUPERISURE SUPERI	
Date / Yime Action / Instruction REAN finali	n .	2 days. (Red \$7	Balai yee n		
1) Colafficer, File Rabitro to? 7)	R-IP	Days Of Repair Resurvey No. of the instantion of	p (\$) w (\$) ws (\$)	Survey Fee: Transpariation: 3+RS_SI Photos Others	
	1				



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Malnine + 65 6383 6280 FaceImile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 579701
59 Loyang Drive Singapore 508069
383 Sin Ming Drive Singapore 575717
Date/Time: 45174dar 1944 52972 360008:23

Page: 1

ARC Repair TP(CFSO)1 JOB CARD Sales Order: 5893269 Am: JC NO305551145 STOMER REGN NO. SHB4946P MILEAGE CITYCAB PTE LTD MAKE TOYOTA 7010070 **FUEL** STOMER NO. 383 SIN MING DRIVE MODEL PRIUS HYBRID (G4A15.04.2025 10:35 Singapore SINGAPORE 575717 65551188 - (R) (O) TARGET DATE YR OF MANU 1.2020 (P) CHASSIS CODE JTDKB3FU003090408 COMPLETION DATE/TIME: COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 15.04.2023

IATURE: 3P.15.04.23

3/NO

LABOR CODE

DESCRIPTION



SERVICE ADVISOR		CUSTOMER'S SIGNATURE
wledgement Slip	Exit Pass	
.: No.: SHB4946P JU TOKIO	Vehicle No.: SHB494	46P
of Service Advisor Signature/Date	Name of Service Advisor	Date

Repairer Estimates

Ref. No:

Date of Loss:

Vehicle Reg. Date:

Gen Condition:

Chassis No:

Driveable?

15/04/2023

14/01/2020

JTDKB3FU003090408

GOOD

YES

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER: CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:

Policy No:

Vehicle Reg. No.:

Party At Fault:

Make/Model: Vehicle Colour:

Odometer:

Engine No:

TOYOTA PRIUS TAXI, 1.8 (A)

YELLOW 2ZR2G10723

THIRD PARTY

SHB4946P

UNKNOWN

0 KM

Paint Type:

List Item Discount:

Total Loss?

Est. Duration of Repair

(day)

25.00 % NO

3

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

		Amount
COST OF CLAIMS		1,023.72
Parts		11.00
Miscellaneous Items		1,400.00
Labour		0.00
Paintwork Labour		0.00
Towing	Gross Total (S\$)	2,434.72
	+ GST 8.00% (S\$)	194.78
¥	Nett Amount (S\$)	2,629.50

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System