

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Apr 2023)

Parts: 144

TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB4946P/17/04/2023 08:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR ASSY RH <i>BOC</i>	25.00	0.00	*1,258.30 FL
2	1		*REAR DOOR APPS LOGO RH <i>NLC</i>	0.00	0.00	*80.00 F
Sub Total (S\$)						1,338.30
- List Item Discount on L Items (S\$)						314.58
Total Parts (S\$)						1,023.72

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB4946P/17/04/2023 08:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING ²⁵⁰	New	600.00
2	SPRAYPAINT ^{250 + 250}	New	600.00
3	ADVERTISEMENT LOGO - DOOR ^{NEL}	New	100.00
4	ADVERTISEMENT LOGO - FENDER REAR ^{NEL}	New	100.00
Gross Labour Cost (S\$)			1,400.00

ComfortDelGro Engineering Pte Ltd/SHB4946P/17/04/2023 08:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 days

L/S

330pm

17/4/23

1rfun

$$T = 2084.72$$

$$20\% = 416.80$$

$$= 1667.20$$

$$= 1650.4$$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: