

ASS. REG. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vehc: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \$ _____

IDAC Accident Report: _____

GIA / PR Secn: _____

Est. Repairs: _____

Lump Sum: _____

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN/OUT

Date/Time

Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.J: (\$ _____)

Veh No: ShB 4946PYr Reg: 14/01/2020Type: MCar / MCycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or _____

Make: Toyota priusCC: 1.718Colour: yellowAC: Insured / Std / NASp. Reading: Unable to StartT/Radio: Insured / Std / NA

Eng/No: _____

C/No: JD1K83FV 0030010408Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NS / SR / STD / A/Rim, orTyre Size: F: 195 / 65 / 195

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PR / SUNI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 15/4/23D.O.L. 17/4/23 330kmSurvey held at ComfortDes. of Damages: Frt / Rear / OPS / NS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Balance: _____

yearly: _____

mv: _____

NV: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RT: \$ _____

Photos: _____

Others: _____

TOTAL: _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Date/Time: 17.04.2023 08:23

Page : 1

AM: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5893269

JC NO305551145

CUSTOMER CITYCAB PTE LTD 7010070 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (R) (P) (O)	REGN NO: SHB4946P	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL: PRIUS HYBRID(G4A15)	DATE/TIME IN: 04.2023 10:35
	YR OF MANU: 14.01.2020	TARGET DATE
	CHASSIS CODE: JTDKB3FU003090408	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 15.04.2023

NATURE: 3P.15.04.23

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHB4946P JU TOKIO

Vehicle No.: SHB4946P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

*Jumani
CL/Sum*

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/04/2023
Vehicle Reg. No.:	SHB4946P	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	14/01/2020
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZR2G10723	Chassis No:	JTDKB3FU003090408
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,023.72
Miscellaneous Items	11.00
Labour	1,400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,434.72
+ GST 8.00% (S\$)	194.78
Nett Amount (S\$)	2,629.50

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System