

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 18/04/2023

To :

Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 29/12/2022

Vehicle No : GBJ-4585-B

Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	TAILLAMP RH	247.00	<i>CMR</i>
1	REAR FENDER RH nn	RESTORE	
	Sub Total	247.00	247
	Discount 10% On Parts	(24.70)	222.30
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	300.00	<i>200</i>
	TO RESPRAY AFFECTED AREAS	300.00	<i>200</i>
			400
			\$622.30
			2 DAYS

Date : 18/04/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 29/12/2022

Vehicle No : GBJ-4585-B Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	600.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

822.30

Remarks:

SUB TOTAL

GST 7.0 % 57.56

TOTAL 879.86

Surveyor's name:

Taufik 97445784

Principal's name: ETHOZ Group Ltd

Taufik e/khanto-wan.

Survey Date & Time:

19/4/23 e 12pm
11/p Resurvey after repair

PAGE : 2