



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI23004003/Uwy3e2 Date: 15/05/2023  Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMD 217S	Veh. Inspected	GBG 9684G
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001322	Excess (\$)	0.00
Assign From	JASMINE LOK	Assign Date	18/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV200 (M)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0148877	Colour	SILVER
Odometer	132146 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	TOURADOR	6 mm
L/H Front Tyre	175/70 R14	TOURADOR	6 mm
R/H Rear Tyre	175/70 R14	TOURADOR	6 mm
L/H Rear Tyre	175/70 R14	TOURADOR	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	10/04/2023	Inspection Date	18/04/2023
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	