

(08/11/13) wef

ASS. REC. BY: John

REF:

CC3/AIS 23004008/Rpa3

4252

C06-2028/009

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKP 88955at Workshop m/s Volkswagenof 247, ALEXANDRA RDInsured: AIS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 27K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 15KVeh No: SKP 88955 Yr Regn: 2014 / OCTType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN GOLF A711413 c.c. 1395Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 135141 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZFW067652

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 14/04/23

Survey held at

ALEXANDRA RD

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 20/04/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 425Z

Vehicle Details

Vehicle No.: SKP8895S

Vehicle to be Exported: No

Intended Deregistration Date: 24 Apr 2023

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF A7 1.4 TSI AT 5G13GZ W/O HID

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: CXS220492

Chassis No.: WVVZZZAUZFW067652

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$19,227.00

Original Registration Date: 20 Oct 2014

First Registration Date: 20 Oct 2014

Transfer Count: 2

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Oct 2024

PARF Rebate Amount: \$2,750.00

Intended COE Rebate Details

COE Expiry Date: 19 Oct 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$62,000.00

COE Rebate Amount: \$9,203.00

Total Rebate Amount: \$11,953.00

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos



Price

\$26,800

Depreciation

\$16,670 /yr

[View models with similar depreciation](#)

Reg Date

26-Sep-2014

(1yr 5mths 1day COE left)

Mileage

134,689 km (15.7k /yr)

Manufactured

2014

Road Tax

\$624 /yr

Transmission

Auto

Dereg Value

\$12,171 as of today (change)

OMV

\$20,782

COE

\$61,899

ARF

\$6,095

Engine Cap

1,395 cc

Power

90.0 kW (120 bhp)

Curb Weight

1,249 kg

No. of Owners

3