

Our .	Job Re	f No 🚼	305551249	ENGINEERING						
Date : 08.05.2023				ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969						
FINALIZATION FORM										
То	LKK			Fax :						
Attn: Toufith			uftkh							
Vehicle Reg No. : SHC291			2911Y			17.04.2023				
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-										
z	The repair job shall bill to:			INCOME		FBN9525X				
2.	The finalized amount shall be:									
	(a)	Spare Parts af	ter List discount			1				
	(b)	Labour Charge	es							
		Total for Part-	By-Part Repair Cost							
	(c.)	Lumpsum Rep	air (if applicable)							
	(0.)		sum repair cost after Less:		-	\$4.050.00				
		Final Lumpsu	in Repair cost			\$1,350.00				
4 . 5 .	7 wor	king days		d Confirmed if there is no reply from you within We confirm the estimates and finalized amount						
	Signat Name	: CHIANG	0	Signature:						
	_	6214831	4	Name : Date :						
Fax : 65468156										
For Official Use Only										
		em	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks				
I. Rental Rate P/Day				YES						
2. Loss of Income Paid				N						
B. Survey Fees			<u>(#)</u>	5.00						
LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun			\$26.75/\$2,00	YES						
lemar					I					

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

MAKE

SHC2911Y

REG 07.11.2019

3

: HYUNDAI IONIO G2

DATE 17.04.2023

MODEL	: HYUNDAI IONIQ G2		CHIANG/INCOME					
Qty	Parts Description/ Labour	Туре	Unit Price	Amount				
1	FRONT DOOR CITY CAB STICKER			× \$75.00				
] 1	FRONT RH WING MIRROR		byco	\$1,391.70				
	SUB TOTAL		1	\$1,466.70				
ļ	LESS 20%			\$293.34				
	DISCOUNTED TOTAL		'	\$1,173.08				
	·							
1	FRONT DOOR ADVERTISEMENT			\$100.00				
	*			\$100.00				
1								
	Labour Charge							
	Panel Beating		3.2	\$450.00				
1	Spray Painting Charge		25	\$400.00				
2 .	TOTAL LABOUR			\$850.00				
	ESTIMATE TOTAL			\$2,123.08				
	Taufili 97495749 WP 16/4/17 C 4 pu fenglin C Whankin 2 days US pesny after report							
1	[au 10 (7 (1)) (1							
1 1	1614/13 c fam							
		-						
	fent in C (Wanpin		91					
	2 obers	- 1						
		1						
	Us permy after repend	- 1						
				1				
1				1				
)								
				i				
1 lat	A		ł					
08/01	~)							
UVV			`					
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will							
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.								
12 - 12 - 13 - 13 - 13 - 13 - 13 - 13 -								