

Your Ref: 202332005032

Date: 22nd May 2023

Our Ref: CS1/AIS23004027/Tvp3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01

Singapore 068897

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PD 1018H
ACCIDENT DATE: 30/01/2023**

We thank you for your instruction on 19/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PD 1018H from M/s Connect3.
- b) Singapore Accident Statement of Vehicle PD 1018H.
- c) Colour damaged vehicle photographs of PD 1018H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PD 1018H
Make & Model	: Zhong Tong Electric LCK6126EVG Auto
Chassis Number	: LDYECS231N0026054
Year of Registration	: 2022
Engine Capacity	: -

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.