

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SNB 7300Lat Workshop m/s PERFORMANCE MOTORof ALEXANDRA RDInsured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 165K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNB 7300L Yr Regn: 2021 SEPType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218I GCMSP c.c. 1499Colour: RED A/C: Insured / Std / NI / NASp. Reading: 19630 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA DAK0207373167Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18R: 2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/04/23

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 80K

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS \$ _____

Photos

Others

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

315, Weyland Road
Singapore 159944
Fax. 64726601 (AfterSales)
Acknowledged by Repairer (Signature)
Signature:
Date: 0020081 - X



GST REG. NO : M2 - 0020081 - X

17 APR 2023

ESTIMATE

Estimate No. : b1 65661
Date Estimated : 17/04/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNB7300L	WBA12AK0207J73167	10/09/2021	218i Gran Coupe	19401

DESCRIPTION

To replace rear bumper and all damage attachment

850 ~~1,700.00~~

To respray rear bumper

986 ~~1,088.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ~~171.00~~

To check electrical wiring

168 ~~171.00~~

Sundries.

? 150.00

Total Labour 1: 3,242.00

DESCRIPTION

REAR BUMPER CARRIER ?

QTY PRIC VALUE

REAR BUMPER BOTTOM TRIM PANEL (M) repair cut

1 505.35 505.35

MOUNTING SMART OPENER (MSP) ?

1 259.15 259.15

REAR BUMPER PANEL PRIMED (MSP/PDC/P repair

1 48.45 48.45

REAR CENTRE GUIDE ?

1 1,360.35 1,360.35

1 163.55 163.55

Total Parts : 2,336.85

Claims OD (3rd Party) Uninsured losses / Direct Settlement

Regn No. 18/04/23 @ 15.50 Claim No.

Date & Time Excess \$

Surveyor's Name RASUL Sign

Surveyor's Tel 90010668 Authorised Yes / No

Authorised Date Time

SURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days

Labour 1 : 3,242.00

Parts : 2,336.85

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 446.31

Grand Total : 6,025.16

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 065W

Vehicle Details

Vehicle No.: SNB7300L

Vehicle to be Exported: No

Intended Deregistration Date: 24 Apr 2023

Vehicle Make: B.M.W.

Vehicle Model: 218I GC MSPT, LED HL, FL

Primary Colour: Red

Manufacturing Year: 2021

Engine No.: 37336467B38A15F

Chassis No.: WBA12AK0207J73167

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$36,321.00

Original Registration Date: 10 Sep 2021

First Registration Date: 10 Sep 2021

Transfer Count: 0

Actual ARF Paid: \$42,850.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Sep 2031

PARF Rebate Amount: \$32,137.00

Intended COE Rebate Details

COE Expiry Date: 09 Sep 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$62,600.00

COE Rebate Amount: \$52,440.00

Total Rebate Amount: \$84,577.00

BMW 218i Gran Coupe M-Sport

[Overview](#)

[Financial](#)

[Insurance](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[M](#)

Price	\$165,600		
Depreciation	\$16,410 /yr View models with similar depre	Reg Date	15-Sep-2021 (8yrs 4mths 21days COE left)
Mileage	16,832 km (10.5k /yr)	Manufactured	2020
Road Tax	\$684 /yr	Transmission	Auto
Dereg Value	\$92,199 as of today (change)	OMV	\$45,451
COE	\$60,109	ARF	\$55,632
Engine Cap	1,499 cc	Power	103.0 kW (138 bhp)
Curb Weight	1,450 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		