

(08/11/13) wof
ASS - REC. BY: PLM

REF: CC4/LPC23004041/R ya3

065w


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SNB 7300L
 at Workshop m/s PERFORMANCE MOTOR
 of MELBOURNE RD
 Insured: LPC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNB 7300L Yr Regn: 2021 SEP
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W 218 IGLMSPT c.c. 1499
 Colour: RED A/C: Insured / Std / NI / NA
 Sp. Reading: 19630 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA 2AK0207J 73167
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/40R18
 R: 2 -

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 165K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>13/04/23</u>	D.O.I. <u>18/04/23</u>
Survey held at <u>PERFORMANCE</u>	
Des. of Damages: Frt / <input checked="" type="checkbox"/> Rear / O/S / N/S / U/C / Rooftop or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT - 80K

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____

1) _____ Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



315, Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Fax. 64796601 (AfterSales)
Acknowledged by Repairer

Signature:

Date:

GST REG. NO : M2 - 0020081 - X

17 APR 2023

ESTIMATE

Estimate No. : b1 65661	Page No. : 1 of 4
Date Estimated : 17/04/2023	
Prepared By : Jack Ng Guo Ming	

- ESTIMATE REPAIR FOR - Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNB7300L	WBA12AK0207J73167	10/09/2021	218i Gran Coupe	19401

DESCRIPTION	VALUE
To replace rear bumper and all damage attachment	850 / 1,700.00
To respray rear bumper	986 / 1,038.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 / 177.00
To check electrical wiring	168 / 177.00
Sundries.	40 ? / 150.00
Total Labour 1:	3,242.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER ? xan	1	505.35	505.35
REAR BUMPER BOTTOM TRIM PANEL (M) repair cut	1	259.15	259.15
MOUNTING SMART OPENER (MSP) ? xan	1	48.45	48.45
REAR BUMPER PANEL PRIMED (MSP/PDC/P repair	1	1,360.35	1,360.35
REAR CENTRE GUIDE ? xan	1	163.55	163.55
Total Parts :			2,336.85

Claims OD (3rd Party) Uninsured losses / Direct Settlement

Regn No. 18/04/23 @ 1550 Claim No. _____

Surveyor's Name RASUM Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Expiry Date _____ Time _____

Survey Parts Photo by Surveyor Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,242.00
Parts	:	2,336.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	446.31
Grand Total	:	6,025.16



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **