

(08/11/17)

ASS. REC. BY: Akid kamal

REF: CS/AIS23004050/Wnp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: AIS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YP 8202 B Yr Regn: 28/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hino XZU710R C.C. 4009Colour White A/C: Insured / Std / NI / NASp.Reading 308767 T/Radio: Insured / Std / NI / NAEng/No: N04CUS35534C/No: JHHUCS3H00K0233*79Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Mth / S/Rim / STD A/Rim or _____Tyre Size: F: 7.00 / R16R: 7.00 / R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 13104123D.O.I. 19104123 1600Survey held at Vin's MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
	Exc: \$2.7k	Balance: 56.5M
		Yearly: \$16K
5/5/23	submit lump sum \$ 6000 (with letter)	
		MV: \$73k
		LTA: \$24,299
		NV: \$48,701

Date/Time, File Pass to?

1) 5/5/23

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

SV10234F0007 / Vin's Motor Pte Ltd [575722]
ENTRY DATE & TIME: 15/04/2023 14:14 (SGT)
SUBMITTED BY: Raymond Teo Yun Loong
VERSION: 1 (15/04/2023 14:14 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	15/04/2023 14:14 (SGT)
Reported by	Actual Driver
Date of Accident	13/04/2023 15:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG PIE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP8202B
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	WELDANPOWER ENTERPRISES & ENGINEERING SERVICES PTE LTD
Company Reg No	1XXXXX257G
Email Address	RAMON@WELDAN.COM.SG
Mobile Phone No	(Phone) +65-63036200
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hino
Model	HINO XZU710R-HKFM3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Goods vehicle
Transmission	Manual
CC	4009

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	AIS/2022/0000375/001315

DRIVER

Name of Driver	AHMED MOHAMMAD TANMOY
Passport No/FIN	GXXXX954W
Date Of Birth	31/12/1993

Occupation	Outdoor
Date Of Driving Pass	23/04/2022
Driving experience	1 YEAR
Gender	Male
Mobile Number	(Phone) +65-86497479
Alt. Phone Number	-
Email Address	RAMON@WELDAN.COM.SG
Address	205 UPPER BUKIT TIMAH ROAD, SIM LIAN BUILDING
Address complement	-
Postcode	588181
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SAME AS SKETCH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 14/04/23
 Policyholder's Signature / Date & Time

 14/4
 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Person (Name as in NRIC/ID card)

Sketch Plan



SKETCH PLAN #2

Describe Circumstance of the Accident

~~I~~ REFER STATEMENT.

VEHICLE TOWED IN TO MY WORKSHOP
K-Kun HIN AUTO PTE LTD FROM SCENE
ON 13.4.2023.

Declaration
(We declare the foregoing particulars are true in every respect)


14/4/23
Policyholder's Signature / Date & Time


14/4
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Person
(Name as in NRIC/ID card)

2

STATEMENT BY DRIVER OF YP8202B INVOLVED IN AN ACCIDENT ALONG P.I.E.
ON 13.04.2023 AT 3.20 P.M.

I am AHMED MOHAMMAD TANMOY, FIN: 2721954W, a driver employed by Weldanpower Enterprises & Engineering Services Pte Ltd.

On 13.04.2023 at around 3.25 p.m., as I was driving along the Pan Island Expressway (near to Jalan Bahar) on the left lane, that is near to the road railing, my lorry suddenly veered to the left and hit the railing and landed on the grass verge.

I got down from my lorry and checked the front left side of my lorry was damaged and the front left tyre was punctured. I was alone, there was no passenger in my lorry. There was no collision with other vehicle and there was no injury caused to myself or to any other person.

However, there was a minor scratch to the road railing, it was not dented and there appeared to be no damage to the railing.

On 14.04.2023, I was instructed by my Supervisor and Manager to proceed to make a Police Report, in the belief that I might have caused damage to public property. I proceeded to Ang Mo Kio North Police Neighbourhood Centre, intending to make the Police Report. The Police Officer there told me that in this case I need not make Police Report because I did not cause injury to other persons or damage to other vehicles. The scratches to the railing did not constitute damage to public property. I was turned away by the officer without having to make the report.

That is all I have to say.

Signature: 

Date: 14.04.2023

Name: AHMED MOHAMMAD TANMOY

Witness By: RAMON TAN 

Date: 14.04.2023



Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/042023/6141
Policy No:	AIS/2022/0000375/001315	Date of Loss:	13/04/2023
Vehicle Reg. No.:	YP8202B	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	WELDANPOWER ENTERPRISES & ENGINEERING SERVICES PTE	Contact No:	+6563036200
Driver:	AHMED MOHAMMAD TANMOY		
Make/Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Vehicle Reg. Date:	28/12/2017
Vehicle Colour:	WHITE	Chassis No:	JHHUCS3H00K023379
Engine No:	N04CUS35534		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	SAME AS SKETCH		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	0.00

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Apr 2023)
Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/YP8202B/19/04/2023 09:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER BRC \$740	0.00	0.00	-
2	1		*LH FRONT BUMPER BRACKET ?	0.00	0.00	-
3	1		*LH FRONT BUMPER FOG LAMP ?	0.00	0.00	-
4	1		*LH FRONT BUMPER FOG LAMP BRACKET ?	0.00	0.00	-
5	1		*HEADLAMP LH CW MOTOR SCR \$330	0.00	0.00	-
6	1		*FRONT GRILLE ?	0.00	0.00	-
7	1		*FRONT GRILLE LOGO NEC 68	0.00	0.00	-
8	1		*LH FRONT CORNER PANEL ?	0.00	0.00	-
9	1		*FRONT PANEL ?	0.00	0.00	-
10	1		*FRONT WINDSCREEN GLASS CRK 1350	0.00	0.00	-
11	1		*FRONT WINDSCREEN GLASS MOULDING - TOP NEC 150	0.00	0.00	-
12	1		*FRONT WINDSCREEN GLASS MOULDING - LOWER NEC 150	0.00	0.00	-
13	1		*LH FRONT WINDSCREEN GLASS MOULDING - LOWER NEC 225.10	0.00	0.00	-
14	1		*FRONT WINDSCREEN GLASS SEALANT NEC 60	0.00	0.00	-
15	1		*FRONT WINDSCREEN GLASS DAMPING SEAL NEC 20	0.00	0.00	-
16	1		*LH FORNT WIPER ARM CAP COVER Missing	0.00	0.00	-
17	1		*LH FORNT WIPER BLADE X	0.00	0.00	-
18	1		*LH WING MIRROR - BIG Missing	0.00	0.00	-
19	1		*LH WING MIRROR - ROUND Missing	0.00	0.00	-
20	1		*LH WING MIRROR - STAY Missing	0.00	0.00	-
21	1		*LH WING MIRROR - INNER COVER Missing	0.00	0.00	-
22	1		*LH WING MIRROR - CAP COVER Missing	0.00	0.00	-
23	1		*LH FRONT DOOR DMG 580	0.00	0.00	-
24	1		*LH FRONT DOOR STEP GARNISH X	0.00	0.00	-
25	1		*LH FRONT DOOR STEP GARNISH REFLECTOR Missing X	0.00	0.00	-
26	1		*LH FRONT DOOR SIGNAL LAMP Missing	0.00	0.00	-
27	1		*LH FRONT DOOR VERTICAL OUTER GARNISH ?	0.00	0.00	-
28	1		*LH FRONT DOOR OUTER MOULDING NEC 225.10	0.00	0.00	-
29	1		*LH FRONT DOOR GLASS BRC CRC 250	0.00	0.00	-
30	1		*LH FRONT DOOR GLASS RUN CHANNEL X	0.00	0.00	-
31	1		*LH FRONT DOOR OUTER PULL HANDLE X	0.00	0.00	-
32	1		*LH FRONT DOOR TOP HINGES X	0.00	0.00	-
33	1		*LH FRONT DOOR CHECKER ?	0.00	0.00	-
34	1		*LH FRONT DOOR INNER TRIMBOARD ?	0.00	0.00	-
35	1		*LH FRONT DOOR INNER SPEAKER X	0.00	0.00	-
36	1		*LH FRONT DOOR WEATHERSTRIP NEC 90	0.00	0.00	-
37	1		*LH FRONT DOOR LOWER WHEEL ARCH GARNISH X	0.00	0.00	-
38	1		*LH FRONT DOOR SPLASH SHIELD SCR	0.00	0.00	-
39	1		*AIR CON CONDENSER X	0.00	0.00	-
40	1		*AIR CON DISCHARGE PIPE X	0.00	0.00	-
41	1		*AIR CON LIQUID PIPE X	0.00	0.00	-
42	1		*SIDE GATE RUBBER STOPPER X	0.00	0.00	-
43	1		*SIDE GATE LOWER SAFETY GUARD X	0.00	0.00	-
44	1		*LH FRONT WHEEL RIM DMG 350	0.00	0.00	-
45	1		*LH FRONT SHOCK ABSORBER ?	0.00	0.00	-
46	1		*LH FRONT KNUCKLE ARM ?	0.00	0.00	-
47	1		*LH FRONT KNUCKLE BEARING - BIG ?	0.00	0.00	-
48	1		*LH FRONT KNUCKLE BEARING - SMALL ?	0.00	0.00	-
49	1		*LH FRONT BEARING OIL SEAL ?	0.00	0.00	-
50	1		*LH FRONT LEAF SPRING SHACKLE ?	0.00	0.00	-
51	1		*LH FRONT LEAF SPRING SHACKLE PIN - CENTRE ?	0.00	0.00	-
52	1		*LH FRONT AXLE BEAM ?	0.00	0.00	-
53	1		*LH FRONT AXLE SECURING U BOLT BT 360	0.00	0.00	-

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
54	1		*FRONT TIE ROD END ?	0.00	0.00	-
55	1		*LH FRONT KING PIN LOCK ?	0.00	0.00	-
56	1		*LH REAR TYRE - OUTER DMC 200	0.00	0.00	-
57	1		*LH REAR TYRE - INNER X	0.00	0.00	-
58	1		*LH REAR WHEEL RIM DMC 350	0.00	0.00	-
59	1		*LH REAR WHEEL HUB NEC 180	0.00	0.00	-
60	1		*LH REAR WHEEL BEARING - BIG NEC 50	0.00	0.00	-
61	1		*LH REAR WHEEL BEARING - SMALL NEC 50	0.00	0.00	-
62	1		*LH REAR WHEEL BEARING OIL SEAL NEC 30	0.00	0.00	-
63	1		*LH REAR SHOCK ABSORBER ?	0.00	0.00	-
64	1		*LH REAR AXLE SECURING 'U' BOLT ?	0.00	0.00	-
65	1		*LH REAR LEAF SPRING SHACKLE ?	0.00	0.00	-
66	1		*LH REAR LEAF SPRING SHACKLE PIN (CENTRE) ?	0.00	0.00	-
67	1		*LH REAR AXLE SHAFT ?	0.00	0.00	-
68	1		*REAR AXLE OIL (3 LITRE) ?	0.00	0.00	-
69	1		*BRAKE FLUID (1 LITRE) X	0.00	0.00	-
70	1		*LH REAR WHEEL MUDGUARD X	0.00	0.00	-
71	1		*LH REAR WHEEL MUDGUARD BRACKET SCR 500	0.00	0.00	-
72	1		*REAR REINFORCEMENT BEAM SCR 500	0.00	0.00	-
73	1		*LH TAILLAMP CRC 541-64	0.00	0.00	-
74	1		*LH TAILLAMP BRACKET BT 140	0.00	0.00	-
75	1		*REAR CARGO DECK SECURING 'U' BOLT - FRONT X	0.00	0.00	-
76	1		*LH FRONT TYRE DMC 200	0.00	0.00	-
77	1		*ERP BRACKET X	0.00	0.00	-
Total Parts (S\$)						7689.90.00

Estimates on Miscellaneous Items


There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO SPRAY PAINTING 800	New	-
<u>Labour Items</u>			
2	TO TOW ACCIDENT VEHICLE FROM SCENE TO WORKSHOP 50	New	-
3	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS 800	New	-
4	TO REMOVE AND RENEW AIR CONDENSER, PIPES AND DRYER, VACCUUM AND TOP UP AIR CON GAS X	New	-
5	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST 100	New	-
6	TO REMOVE DOORS FITTINGS X	New	-
7	TO DISMANTLE AND CHECK AND RENEW AFFECTED FRONT UNDERCARRIAGE X	New	-
8	TO DISMANTLE AND CHECK AND RENEW AFFECTED REAR UNDERCARRIAGE X	New	-
9	TO REMOVE, REALIGN REAR CARGO DECK 50	New	-
10	TO FOCUS HEADLAMP AND TAILLAMP, TO CHECK FRONT & REAR LIGHTING OPERATION AND REWIRING 30	New	-
11	TO CONDUCT WHEEL ALIGNMENT TEST 50	New	-
Gross Labour Cost (S\$)			1 830 0.00

Vin's Motor Pte Ltd/YP8202B/19/04/2023 09:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

05 days 
Akid 8700 5631
19104123 1630

**Post an Advertisement**

Sell it yourself! Advertise it at just

\$68 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**Land Rover Defender 90 Puma (COE Till 04/2029)**

Original Ivory White Beauty. 1
Lady Owner. Never Been Off
Road. Direct Owner.
Direct Owner StarAd

Sort by results/page**2 vehicles**[Advanced Search](#)[Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hino XZU710R		Any	Any	2017	Any	Any	Any	Available
	Hino XZU710R		\$66,000	\$16,780 /yr	27-Mar-2017	4,009 cc	53,000 km	Truck	Available
	Fuel Type: Diesel Low mileage of 53,000 km only. 1 owner. 15 feet high deck wooden body lorry attached with canopy. Can drive with Class 3 licence. Carr... Posted: 15-Apr-2023								
	Hino XZU710R		\$72,800	\$16,540 /yr	14-Sep-2017	4,009 cc	-	Truck	Available
	Fuel Type: Diesel Rare Auto Gear 14 feet Truck, Full Auto Transmission Gearbox by Toyota, Very Smooth Gear Change Unlike Other Models that Uses Semi... Posted: 31-Mar-2023								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads** results/page**Buy / Rent Cars**[New Cars For Sale](#)[Used Cars For Sale](#)[Cars For Rent](#)**Sell Your Car**[Post an Ad](#)[Sell by Bidding](#)[Sell by Consignment](#)**Aftermarket**[Workshop Directory](#)[Aftermarket Products](#)**Articles**[Car Reviews](#)[Car Advice](#)[Car News](#)[Car Features](#)**General**[About Us](#)[Contact Us](#)[Careers](#)[Site Map](#)**Resources**[COE Prices](#)[Car Loan Calculators](#)[Car Forum](#)[Car Insurance](#)[Car Valuation](#)[COE Renewal](#)[Used Car Warranty](#)[Bidded Carplates](#)[Carpark Rates](#)**Follow Sgcarmart.com**[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	257G
Vehicle Details	
Vehicle No.:	YP8202B
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Apr 2023
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	N04CUS35534
Chassis No.:	JHHUCS3H00K023379
Maximum Power Output:	-
Open Market Value:	\$30,554.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,528.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$51,890.00
COE Rebate Amount:	\$24,299.00
Total Rebate Amount:	\$24,299.00

The information contained herein is correct as at 19 Apr 2023

OK