



SV AUTOWORKS PTE LTD

UEN No.: 202140260K

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6242 4328

Email: info.svautoworks@gmail.com

Our Ref.: SME 2476 S

Your Ref.: _____

Date: 27/05/2023

ATTN: Motor Claims Department

INS: Allianz Insurance Singapore Pte Ltd

Dear Sir/Madam,

Accident Involving: SME 2476 S & SMY 4983 B

Date of Accident: 13/02/2023 @ 07:40 Hrs

Location: Pie towards cte singapore

We refer to the above-mentioned accident.

We are claiming as follows:

Cost of Repair: \$ 26,000.00

Own Damage Excess: \$ 1,500.00

Total: \$ 24,500.00

Towing Fee: \$ 60.00

Towing Fee: \$ 50.00

STA Inspection Fee: \$ 224.64

Grand Total: \$ 24,834.64

BASED ON NIMA PROTOCOL, YOU HAVE 8 WEEKS TO RESPOND. FAILURE IN COMPLIANCE AND OUR LEGAL SOLICITOR/S WILL TAKE OVER THE CASE IN FULL

The above-mentioned settlement is in respect for our client of damage pertaining to his/her motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his/her personal injuries.

Kindly take note that our office is located at **8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24, Singapore 415875.**

For any further queries, please kindly contact SV @ 6242 4328, or email to info.svautoworks@gmail.com

Thank You,

SV Autoworks Pte Ltd





SV AUTOWORKS PTE LTD

UEN No.: 202140260K

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6242 4328

Email: info.svautoworks@gmail.com

TAX INVOICE

Allianz Insurance Singapore Pte Ltd

6297 8802

Invoice No. : SV2023 593 05
Invoice Date : 27 May, 2023
Vehicle No. : SME 2476 S
Make & Model : RENAULT GRAND SCENIC IV 1.5
Chassis No. : VF1RFA00059238203
Mileage :-
Terms : Due within 90 days

NO.	DESCRIPTION	QUANTITY	PER UNIT (SGD)	AMOUNT (SGD)
1	To Carry Out Repair & Respray on Accident Corresponding to Supply on Spare Parts & Labour Charges	1	26,000.00	26,000.00
2	Own Damage Excess	1	1,500.00	1,500.00

GRAND TOTAL : **\$24,500.00**

Amount Paid \$0.00

Balance Due \$24,500.00



Signature/Company Stamp

I agree to the price as listed above and affirm that the goods are received in good condition.



SV AUTOWORKS PTE LTD

UEN No.: 202140260K

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6242 4328

Email: info.svautoworks@gmail.com

TAX INVOICE

Allianz Insurance Singapore Pte Ltd

6297 8802

Invoice No. : SV2023 594 05
Invoice Date : 27 May, 2023
Vehicle No. : SME 2476 S
Make & Model : RENAULT GRAND SCENIC IV 1.5
Chassis No. : VF1RFA00059238203
Mileage : -
Terms : Due within 90 days

NO.	DESCRIPTION	QUANTITY	PER UNIT (SGD)	AMOUNT (SGD)
1	Towing Fee (Frm: Sin Ming Autocity to Premier 02-24)	1	60.00	60.00
2	Towing Fee (Frm: Premier 02-24 to Autobay 01-66)	1	50.00	50.00
3	STA Inspection Fee	1	224.64	224.64

GRAND TOTAL	\$334.64
Amount Paid	\$0.00
Balance Due	\$334.64



Signature/Company Stamp

I agree to the price as listed above and affirm that the goods are received in good condition.

LETTER OF AUTHORISATION

Accident on 13/02/2023 @ 07:40 Hrs along P1E Towards CTE Singapore
involving vehicles nos. SME 2476 S x SMY 4983 B

In consideration of **SV Autoworks Pte. Ltd.**, 8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24, Singapore 415875, repairing my/our motor vehicle no. SME 2476 S at my/our request, I/We, GIS MOTORING PTE LTD ("the claimant") of

(address) bearing NRIC no. 201803437N the owner of motor vehicle no. SME 2476 S, hereby authorise them to demand claim, settle and receive whatever amount settle payable by the insurance company or third party or commence legal proceeding for cost of repairs, loss of use and etc, to any of their appointed advocates to act of me/us in respect of the said accident/claim and all the amount claimed or settled shall belong and make payable to them absolutely by the insurance company of the third party. I/We further authorised them to give an absolute discharge on my/our behalf and to sign discharge voucher(s) and any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

I/We further agree to fully co-operate and attend all court hearings that are necessary to prosecute the claims maintained by **SV Autoworks Pte. Ltd.** I/We further agree and undertake to indemnify them against my/our claim for costs which arise therewith. In the event that my/our claim is unsuccessful, I/we undertake to pay to **SV Autoworks Pte. Ltd.** the cost of repairs of my/our vehicle. In the event that settlement cheque were to be drawn in my/our favour, I/we hereby give my/our instruction to clear the said cheque on my/our behalf by presenting the same for payment directly into **SV Autoworks Pte. Ltd.** account. Upon clearance of the said cheque, I/we further **SV Autoworks Pte. Ltd.** and/or their appointed law firm to utilise the monies to pay their charges without further reference to me. I confirm that the payment to **SV Autoworks Pte. Ltd.** shall amount to a good discharge of **SV Autoworks Pte. Ltd.** and/or their appointed law firm's obligation to me in respect of the settlement monies.

Dated this 13 day of 02 (month) 2023 (year).

"The Claimant's" Signature

Name: GIS MOTORING PTE LTD

NRIC No.: 201803437N

SV Autoworks Pte. Ltd.

Name: SV



TAX INVOICE

SV Autoworks Pte Ltd
8 Kaki Bukit Avenue 4,
#02-24 Premier Kaki Bukit
Singapore 415875

Invoice Date
26 May 2023

Invoice Number
INV-0033873

Reference
SME2476S-SN:007939

Complete Evaluation
201500060W

Complete Evaluation Pte Ltd
c/o STA Evaluation
13 Kaki Bukit Road 4,
#01-02, Bartley Biz Centre,
Singapore 417807
Phone: 6264 0606

GST Reg No: 201500060W

Description	Quantity	Unit Price	Tax	Amount SGD
Evaluation Package A - KB	1.00	208.00	8%	208.00
Subtotal				208.00
Total Local supply of goods and services 8%				16.64
Invoice Total SGD				224.64
Total Net Payments SGD				224.64
Amount Due SGD				0.00

Due Date: 26 May 2023

Cheque Payable to "Complete Evaluation Pte Ltd"
Payment Mode Available at Centres: PayNow / Cheque



PAYMENT ADVICE

To: Complete Evaluation Pte Ltd c/o STA Evaluation
13 Kaki Bukit Road 4, #01-02,
Bartley Biz Centre
Singapore 417807

Customer SV Autoworks Pte Ltd

Invoice Number INV-0033873

Amount Due 0.00

Due Date 26 May 2023

Amount Enclosed

Enter the amount you are paying above

This
REPORT

has been awarded to

Vehicle No: SME2476S
Make & Model: RENAULT GRAND SCENIC IV 1.5
Date: 26/5/2023

For the Evaluation (Full)

by

The Used Car Evaluation Specialist

OVERALL GRADING			
☆☆☆☆	☆☆☆	☆☆	☆
	B		

- Note: 1. This Evaluation does not include all the required Tests for the LTA Road Worthiness Inspection which is also available LTA Vehicle Inspection package, please check with our friendly STA Evaluation staff.
2. This is NOT a LTA Road Worthiness Inspection Certificate and NOT valid for Road Tax Renewal.

EVALUATION REPORT

Vehicle Details

Vehicle Number: SME2476S
Engine Number: K9KF649D021403
(Extracted from OneMotoring)
IU Number: 1128031927
Inspection Due Date: 25 Dec 2023

Chassis Number: VF1RFA00059238203
(Extracted from OneMotoring)
Mileage (Before Evaluation): 307547 KM
Registration Date: 26 Dec 2017

Photo - Front View



Photo - Rear View



Photo - Chassis Number



Photo - Dashboard (Ignition Only)



Photo - Engine Bay View



Photo - Dashboard Engine Running



Summary Report

Form T-STAI-WI-EVAL-001-02 Rev 00



EVALUATION REPORT

1 Chassis Frame Inspection

Frame Measurement	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Crack Damaged	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Repair Welding Mark	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Chassis Frame Number	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

2 Undercarriage

Front Rear panels	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Chassis legs	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Sub frame	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Coil Spring & Shock Absorbers	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Brake lines Linkages	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Control arm bushes	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Oil sumps	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Mountings	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Racks and Pinion	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Drive shafts	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Ball Joint Tie rod end	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Exhaust system	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Exhaust pipe rubber hanger	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Floorboard	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

3 Rims, Tyres and Brake Rotor

Rims	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Tyres	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Brake Rotors	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

4 Engine Bay

Engine	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Transmission Box	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Battery	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
HID Ballast Bulb	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Auxillary belts	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Pumps	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Radiator tank, cap, hoses	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Aircon compressor	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Alternator	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

Summary Report

Form T-STAI-WI-EVAL-001-02 Rev 00



EVALUATION REPORT

5	Fluid Level			
	Engine oil	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Power Steering oil	<input type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Transmission oil	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Brake fluid	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Clutch oil	<input type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Coolant	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
6	Boot			
	Electric tailgate	<input type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Battery	<input type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Weather seal	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Rear sills & Spot welds	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Sealant & silicon	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Spare Tyres & Spare Tyres repair kit	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
	Tools & kit	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/> Fail <input type="checkbox"/> NA
7	Bodyworks			
	Front windscreen	PASS	%	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Front windows	PASS	%	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Rear windows	PASS	%	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Rear windscreen	PASS	%	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Bonnet			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Bumper			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Fenders			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Doors			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Roof			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Boot			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Head Tail lights assembly			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Number plate			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Front OPC seal	ROV	<input type="text"/>	<input type="checkbox"/> Pass <input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Rear OPC seal	ROV	<input type="text"/>	<input type="checkbox"/> Pass <input type="checkbox"/> Fail <input checked="" type="checkbox"/> NA
	Door side sill & Spot welds			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Weather Seal			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
8	Interior			
	Horn			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Headlights Tailights			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Signal lights			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Hazard lights			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Warning light error message			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Washer wiper			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Electrical wing mirrors			<input type="checkbox"/> Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> NA
	Functionality Power windows			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Aircon			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Parking Brake			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Functionality Doors			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Seats Adjust			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA
	Seats belts buckle			<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> NA

Summary Report

Form T-STAI-WI-EVAL-001-02 Rev 00



EVALUATION REPORT

Battery Testing

Vehicle number SME2476S

Date created 26/5/2023

Photo - Battery Test



- 7 Without limiting the generality of the above and subject to clause 8 below, STA's AGGREGATE LIABILITY TO YOU (IF ANY), IN CONTRACT OR TORT OR UNDER STATUTE OR AT LAW OR OTHERWISE, FOR ANY LOSS OR DAMAGE SUFFERED BY YOU (OR BY ANY OTHER PARTY) ARISING FROM OR IN CONNECTION WITH THE EVALUATION/ASSESSMENT SERVICES, HOWEVER THE LOSS OR DAMAGE IS CAUSED, INCLUDING OUR NEGLIGENCE, SHALL BE LIMITED TO 10X THE EVALUATION FEES PAID BY YOU. HOWEVER THIS LIABILITY DOES NOT IN ANYWAY EXTEND COVER WEAR AND TEAR ITEMS FOR WHICH NO LIABILITY EXISTS.
- 8 If you are unsatisfied with the certificate/assessment report and felt you have suffered loss or damage and have a valid claim, you shall notify STA immediately when the claim arises and the motor vehicle must (unless otherwise agreed by STA) be brought back to STA for verification of your claim by the next working day. STA shall have the right (but not the obligation) to have the vehicle serviced/repared to the condition certified in the assessment report if it determines in its sole discretion that there is a manifest error in the certificate/assessment report issued. Upon completion of service/repair, no other claim shall be made by the customer or any other party relating to the evaluation/assessment services rendered or the assessment report/certificate issued.
- 9 Vehicle parked overnight at our premises will be at customers owners own risk. STA are not liable to you or any person with you for damage to, destruction of, theft of or delivery up of any property (including anything in or on your vehicle or any other vehicle); however caused, and you release and indemnify us from any claim which you might otherwise have against us. We will not be liable to you for delivery of your vehicle to any person who did not have authority to take your vehicle and even if the person taking the vehicle does not have your authority.

I, the under-mentioned customer, unconditionally agree to the foregoing terms and conditions and hereby request that an evaluation of my motor vehicle be conducted.

Time in 26/5/2023 3:12:30 pm Time out (Printed) 26/5/2023 5:27:12 pm

Signature _____

Name Lim Wee Leng Tel 8188 0381

Mileage after 307549 KM

Company SV Autoworks Pte Ltd

Co.Address 8 Kaki Bukit Avenue 4, #02-24 Premier Kaki Bukit Singapore 415875

Date created 26/5/2023




Car-O-Liner Vision2 X3

Lower body Repair Report

2.11.0.3 t:0
2023-05-26

Customer		DataSheet 18:136	Vehicle
Name SV AUTOWORKS PTE LTD		Make Renault	Issue 2019-04-01
Address	Zip	Model Scenic IV	Type 5D/FWD
City	Phone	Year 2016-2022	VIN
State		License No. SME2476S	Miles
E-mail			
Insurance		Job	
Insurance Co	Claim No	Start Date 2023-05-26	
Adjuster	Phone	End Date 2023-05-26	
E-mail			



BodyShop	Notes
Company STA Inspection Centre Address 13 KAKI BUKIT ROAD 4, #01-02 City SINGAPORE Zip 417807 State Phone 63840606 E-mail information@stai.com.sg	WITH IN ACCEPTABLE TOLERANCE



PRINCE TOWING SERVICES

CO REG NO: 53405980E

PRINCETOWING.SERVICES@GMAIL.COM/ +65 9222 7993

NO. 10465

DATE: 21/4/23



M/S

VEHICLE NO

FROM

TO

REMARKS

SV

SME 24765

Singapore Autocity

Premier 02-24

MODEL

SCENIC

CALL TIME


1600

TIME ARRIVAL

1700

ARRIVAL WORKSHOP

1740



☐ CHANGE TYRES/PATCH TYRES

☒ ACCIDENT



☐ USE CAR CARRIER

☐ LOADED

☐ BASEMENT/MULTI CARPARK

☐ LOW BODY KIT/LOW SPOILER

☐ OPEN DOOR

☐ JUMP START

☐ USING KING DOLLEY

☐ DISMANTLE BRAKE/SHAFT

☐ CRANE UP/WINCH OUT

AMOUNT S\$

60k

Shen

RECEIVED BY

PRINCE TOWING



PRINCE TOWING SERVICES

CO REG NO: 53405980E

PRINCETOWING.SERVICES@GMAIL.COM/ +65 9222 7993



NO. 10693

DATE: 15/5/23

M/S

VEHICLE NO

FROM

TO

REMARKS

SV AUTO

SME 2476 S

8 PREMIER 02-24

AURORA 01-66

MODEL

CALL TIME

TIME ARRIVAL


ARRIVAL WORKSHOP

REM47

1400

1500

1540



- ☐ CHANGE TYRES/PATCH TYRES ☐ ACCIDENT ☐ USE CAR CARRIER ☐ LOADED
- ☐ BASEMENT/MULTI CARPARK ☐ LOW BODY KIT/LOW SPOILER ☐ OPEN DOOR ☐ JUMP START
- ☒ USING KING DOLLEY ☐ DISMANTLE BRAKE/SHAFT ☐ CRANE UP/WINCH OUT

AMOUNT S\$

\$50

~~100~~

RECEIVED BY

Jim

PRINCE TOWING