



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23004113/Tvp3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 05-05-2023

Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | YQ 4039C       | Veh. Inspected | SHA 6949Z  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1219423-002 | Excess (\$)    | 0.00       |
| Assign From  |                | Assign Date    | 20/04/2023 |

### 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | HYUNDAI IONIQ     | c.c          | 1580     |
| Engine No.   | HIDDEN            | Year of Reg. | 2019     |
| Chassis No.  | KMHC851CVKU146258 | Colour       | BLUE     |
| Odometer     | 622785            | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

### 3. Conditions of Tyres

|                | Size       | Make      | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm    |
| L/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm    |
| R/H Rear Tyre  | 195/65 R15 | WEST LAKE | 6 mm    |
| L/H Rear Tyre  | 195/65 R15 | WEST LAKE | 6 mm    |

### 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 20/04/2023                                                               | Inspection Date | 20/04/2023 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|