

ASS. REC. BY: Taj

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Lim TSVeh No: SMC 1766GYr Regn: 2017 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 573649

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDICKSF4X03090481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 20/4/25Survey held at Wong T. Leung

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S. + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.I. (%)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KLV

REPAIR ESTIMATE

DATE: 20.04.2023

SKM8615A

INSURANCE: INCOME (L5)

MODEL: Toyota Prius G4A

MVA: LIM T S

VEHICLE NO.: SHC1766G

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk Outer Garnish	1		\$1,054.71 <i>Re</i>
	Rear Trunk Lid Logo (Prius)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Hybrid)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Toyota Star)	1		\$81.43 <i>x</i>
	Rear Bumper	1		\$551.89 <i>de</i>
	Rear Bumper Re-Inforcement	1		\$378.32 <i>bf</i>
	Rear Bumper Lower Cover-Black	1		\$654.96 <i>de</i>
	Rear Bumper Under Floor Cover	1		\$425.25 <i>mis</i>
	Rear Bumper Reflector RH / LH	2	\$55.00	\$110.00 <i>x</i>
	Rear Bumper Side Brkt RH / LH	2	\$112.70	\$225.40 <i>x</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>net</i>
	Rear Bumper Tow Cover	1		\$82.70 <i>mis</i>
	SUB TOTAL			\$3,710.94
	LESS 25%			\$927.74
	DISCOUNTED TOTAL			\$2,783.20
	Reverse Sensor	1		\$135.70 <i>net</i>
	Rear Trunk ComfortDelGro	1		\$30.00 <i>net</i>
	Rear Trunk 65521111	1		\$30.00 <i>net</i>
	Rear Trunk ZIG APPS	1		\$40.00 <i>net</i>
	SUB S/NETT			\$235.70
	LESS 10%			\$23.57
	S/NETT TOTAL			\$212.13
	Rear Bumper Mat	1		\$50.00 <i>net</i>
	TOTAL SPARE PARTS			\$3,045.33
	Labour Charge			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	TOTAL LABOUR			\$1,520.00
	ESTIMATE TOTAL			\$4,565.33

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota Prius

Date/Time: 20.04.2023 14:55

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5893786

JC NO305551915

CUSTOMER MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. SHC1766G	MILEAGE
	MAKE TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4A20.04.2023 13:05	DATE/TIME IN
	YR OF MANU. 19.12.2019	TARGET DATE
	CHASSIS CODE JTDKB3FUX03090481	COMPLETION DATE/TIME:

COUNT CARD NO.

Accident Date: 20.04.2023

NATURE: 3P 20.04.2023 LKK-


W/NO LABOR CODE
000010 PB

JOB DESCRIPTION

LS
Income

DESCRIPTION
LUMPSUM REPAIR-SHC1766G-TP

SKM
8615A



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHC1766G LIMITS

Vehicle No.: SHC1766G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard