

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC23004117/Avy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	22/06/2023	
	ATTN: NATALIE LI	EE		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMM 1107Y	Veh. Inspected		SLQ 3589S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1219078-002	Excess (\$)		0.00	
	Assign From	HAZALYSA	Assign Date		20/04/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0157493	Colour		BLACK	
	Odometer	358648 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
					12	
5.	General Information					
	Accident Date	19/04/2023	Inspect Date / T	Γime	21/04/2023 (02:17 PM)	
	Survey held at	d at JL PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
Ц	1					