

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 19/04/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 09/04/2023

Vehicle No : GBJ-1201-D

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Special Nett Item			
1	REAR ALUMINIUM CABIN BOX DOOR RH <i>bt/</i>	500.00	350
2	REAR ALUMINIUM CABIN DOOR HINGES RH <i>bt/</i>	220.00	150
1	REAR ALUMINIUM CABIN BOX DOOR LH <i>bt/</i>	500.00	350
1	REAR CABIN BOX SIDE PILLAR RH <i>bt/</i>	400.00	200
1	REAR CABIN BOX LOCK ARM LEVER <i>repair</i>	280.00	X
1	REAR CABIN BOX LOCK LEVER HOLDER RH <i>MIS</i>	80.00	40
2	REAR END PANEL RUBBER DAMPER RH/LH <i>bro</i>	200.00	120
1	REAR END PANEL <i>bt/</i>	500.00	300
1	REAR ADVERTISEMENT PANEL <i>new</i>	350.00	300

Date : 19/04/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 09/04/2023

Vehicle No : GBJ-1201-D

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	70 KM/HR <i>not</i>	10.00	
1	13 PAX STICKER <i>not</i>	10.00	
	Sub Total	3050.00	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	600.00	500
	TO RESPRAY AFFECTED AREAS	600.00	500
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	X

Date : 19/04/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 09/04/2023

Vehicle No : GBJ-1201-D

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

1230.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4,280.00

Remarks:

6 days / Lump sum

SUB TOTAL

GST 8.0 % 342.40

TOTAL 4,622.40

Surveyor's name:

RASUL - Hp 9000068

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

20/04/23 @ 1600