

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23004141/Awy3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	20/06/2023	
			Code	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLZ 8783S	Veh. Inspected	SMM 5934A	
	Policy No.	P10561408R01	Coverage (\$)	0.00	
	Claim No.	C10021824/JL	Excess (\$)	0.00	
	Assign From	DON BONG	Assign Date	21/04/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI ATTRAGE	c.c	1193	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MMBSTA13AKH002203	Colour	GREY	
	Odometer	95092 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/55 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/55 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/04/2023	Inspection Date	21/04/2023	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: