REF: CS/G	RB23004148/Avy3
ss. PECBY:	
	ASSIGNMENT
rom : Date:	Veh No: SBH 138X Yr Regn: 2019 10ct.
stim ated Cost:	Type M.Can / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
D / TP/WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
Inspect Vehicle No:	Make: BMW 216; c.c 1499
Workshop m/s	Colour Bue - A/C: Insured / Std / NI / NA
	Sp.Reading 62760 T/Radio: Insured / Std / NI / NA
sured: SLK 7337H	Eng/No:
licy No.	C/No: WBA6V120205N97926.
aim: S No. D21MFL0000447_02	Gen. Copd. Good / Fair / Poor / Burnt
ım (nsured; Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder / Jammed / Leaked / Burnt or
ake of Veh:	Modí: Nil /S/Rim / STD A/Rim or
-	Tyre Size: F: 205/55 R17
(Policy Condition)	R: 205/55R17.
emark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continental
al. or Market Value:	Front Rear
AC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
IA / PR Seen: Consistent?: Yes or No st Renairs: days Res.: Yes or No	D.O.A. 19/4/2023 D.O.I. 21/024 23.
	Survey held at 1-149 Mey ,
um Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or
A / REV / REP. / 24 HRS	IN / OUT
ate:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
7/0/00	(D-10550 57, 50%)
7/6/23 Adrian confirmed lump sum \$6500	(Red 9558.57, 59%)
M√ :	
PV:	
Nett:	
ate/Time, File Pass to? : Preli. Report	Days Of Repair: 6
: Final Report	Resurvey No. of Trip: Survey Fee:
ate/Time, File Return to?	Transportation:
27/6/23-typist	Add Fee:: Site Insp (\$)8+RSSI
	: Interview (\$ ) Photos
oport Formet: TP	: Fech. Invs (\$ ) Others