

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305551910
Date : 20-04-23
Time of Fax : _____

Via Fax : EMAIL
Your Insured : SGH 9619G
Date of Acc : 19-04-23

Attn: Motor Claims Department

ALLIANZ

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 9326 B

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5893716

JC NO305551910

OMER

S CITYCAB PTE LTD

OMER NO 7010070

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65551188

(P) (O)

DUNT CARD NO.

REGN NO.

SHA9326B

MILEAGE

MAKE

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)19.04.2023 15:40

DATE/TIME IN

YR OF MANU

05.09.2017

TARGET DATE

CHASSIS CODE

JTDB3FU803562760

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 19.04.2023

ATURE: 3P.19.04.23

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHA9326B

JU ALLIANZ

Vehicle No.:

SHA9326B

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

DATE: 20.04.23

MVA JUMANI

DOA: 19.04.23

ALLIANZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$503.04
1	REAR BUMPER CENTRE MLDG			\$654.96
1	REAR BUMPER BEAM			\$378.32
10	REAR BUMPER CLIPS			\$22.00
	SUB TOTAL			\$1,558.32
	LESS 25%			\$389.58
	DISCOUNTED TOTAL			\$1,168.74
	Labour Charge			
	PANEL BEATING –			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	ADVERTISEMENT LOGO - FENDER			\$200.00
	TOTAL LABOUR			\$950.00
	ESTIMATE TOTAL			\$2,118.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				