



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23004231/Nnp3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 15-05-2023

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMQ 3896T	Veh. Inspected	SHC 3171J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1219801-002	Excess (\$)	0.00
Assign From		Assign Date	24/04/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ G3	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU187643	Colour	YELLOW
Odometer	448181	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	8 mm
L/H Front Tyre	195/65 R15	WEST LAKE	8 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	8 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/04/2023	Inspection Date	24/04/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------