

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305552365  
Date : 02.05.2023

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHC3171J

Date of Accident : 23.04.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME SMQ3896T

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (Include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$4,800.00

Final Lumpsum Repair cost \$4,800.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM TS

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 25/2023

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee / GEARS	\$26.75 / \$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: