

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LIBERTY INSURANCE PTE LTD	Affiliated to Federation Internationale Des Experts En Automobile						
Code: LIP		LIBERTY INSURAN	NCE PTE LTD	Ref:	CS3/LIP22012377/Tqy3m4-1		
Policy Particulars :- THIRD PARTY CLAIM				Date:	15/06/2023		
Insured Veh.				Code:	LIP		
Policy No.   SD22V15432/VCH/R00   Coverage (\$)   0.00     Claim No.   AVS22/3431   Excess (\$)   0.00     Assign From   ANDY SEAH   Assign Date   21/04/2023     2.   Vehicle Particulars & Condition     Make & Model   FORD RANGER 2.0 D C   c.c   1996     Engine No.   HIDDEN   Year of Reg.     Chassis No.   AFAPXXMJ2PKS29579   Colour   BLACK     Odometer   73344 KM   Steering   IN ORDER     Brakes   IN ORDER   Modification   NIL     General   GOOD     3.   Conditions of Tyres	1.	Policy Particulars :- THIRD PARTY CLAIM					
Claim No.		Insured Veh.	GBK 5633J	Veh. Inspected	GBJ 9867E		
Assign From ANDY SEAH Assign Date 21/04/2023  2. Vehicle Particulars & Condition  Make & Model FORD RANGER 2.0 D C c.c 1996  Engine No. HIDDEN Year of Reg.  Chassis No. AFAPXXMJ2PKS29579 Colour BLACK  Odometer 73344 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres    Size Make Balance		Policy No.	SD22V15432/VCH/R00	Coverage (\$)	0.00		
2. Vehicle Particulars & Condition  Make & Model FORD RANGER 2.0 D C c.c 1996  Engine No. HIDDEN Year of Reg.  Chassis No. AFAPXXMJ2PKS29579 Colour BLACK  Odometer 73344 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres    Size   Make   Balance		Claim No.	AVS22/3431	Excess (\$)	0.00		
Make & Model   FORD RANGER 2.0 D C   C.C   1996		Assign From	ANDY SEAH	Assign Date	21/04/2023		
Engine No. HIDDEN Year of Reg. Chassis No. AFAPXXMJ2PKS29579 Colour BLACK Odometer 73344 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD  3. Conditions of Tyres  R/H Front Tyre 265/65 R17 YOKOHAMA 6 mm L/H Front Tyre 265/65 R17 YOKOHAMA 6 mm L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 05/12/2022 Inspection Date 12/12/2022 Survey held at SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	2.	2. Vehicle Particulars & Condition					
Chassis No. AFAPXXMJ2PKS29579 Colour BLACK  Odometer 73344 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres    Size   Make   Balance		Make & Model	FORD RANGER 2.0 D C	c.c	1996		
Dodometer		Engine No.	HIDDEN	Year of Reg.			
Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres    Size   Make   Balance		Chassis No.	AFAPXXMJ2PKS29579	Colour	BLACK		
3. Conditions of Tyres    Size		Odometer	73344 KM	Steering	IN ORDER		
3. Conditions of Tyres    Size   Make   Balance		Brakes	IN ORDER	Modification	NIL		
R/H Front Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Front Tyre 265/65 R17 YOKOHAMA 6 mm  R/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT		General	GOOD				
R/H Front Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Front Tyre 265/65 R17 YOKOHAMA 6 mm  R/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT	3. Conditions of Tyres						
L/H Front Tyre 265/65 R17 YOKOHAMA 6 mm  R/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT			Size	Make	Balance		
R/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT		R/H Front Tyre	265/65 R17	YOKOHAMA	6 mm		
L/H Rear Tyre 265/65 R17 YOKOHAMA 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT		L/H Front Tyre	265/65 R17	YOKOHAMA	6 mm		
4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT		R/H Rear Tyre	265/65 R17	YOKOHAMA	6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4  #02-24 PREMIER @ KAKI BUKIT		L/H Rear Tyre	265/65 R17	YOKOHAMA	6 mm		
DAMAGES SEE DETAILS.  5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	4.						
5. General Information  Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT		THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.					
Accident Date 05/12/2022 Inspection Date 12/12/2022  Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT		DAMAGES SEE DETAILS.					
Survey held at SV AUTOWORKS PTE LTD  8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	5.						
8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT		Accident Date	05/12/2022	Inspection Date	12/12/2022		
#02-24 PREMIER @ KAKI BUKIT		Survey held at	SV AUTOWORKS PTE LTD				
CITOTO TICE TICOTO			#02-24 PREMIER @ KAKI BUKI	Т			
5a. Remarks	5a.						
A)REGISTRATION DATE: 31 OCT 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b. Estimate Days of Repair	5b.						
ESTIMATED NORMAL PERIOD FOR REPAIR: 18 Working Days							