

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMR 359S

Policy No. _____

Claims No. MT/1219059-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 6388L Yr Regn: 2011 10CT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: HYUNDAI IONIQ 1.6 80T c.c. 1580

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 292478 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB51CVLUM94948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NR / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/04/23 D.O.I. 19/04/23

Survey held at COMFORT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/4/23 Rasul confirmed final fig \$2775.50 (Red 458.14, 14%)

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) 4/5/23-typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation: _____

S + RS _____ \$

Photos

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format : TP

Lump Sum / I.B.I: (\$ 2775.50)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHB6388L**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **19.04.23**
 MVA **JUMANI**
 DOA: **19.04.23**

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>de</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>sur</i>			\$451.25
1	REAR BUMPER BEAM ?			\$394.80
10	REAR BUMPER CLIPS <i>na</i>			\$22.00
1	FOG LAMP REAR <i>x</i>			\$201.50
1	ANTENNA SMARTKEY ?			\$40.50
1	BOOTLID EMBLEM - IONIQ <i>na</i>			\$31.30
1	BOOTLID EMBLEM - HYBRID <i>na</i>			\$24.30
1	BOOTLID EMBLEM - H <i>na</i>			\$28.00
	SUB TOTAL			\$1,653.05
	LESS 20%			\$330.61
	DISCOUNTED TOTAL			\$1,322.44
1	REAR NUMBER PLATE <i>sur</i>			\$50.00
1	REVERSE SENSOR ?			\$180.00
1	BUMPER MAT <i>de</i>			\$50.00
	BOOTLID COMFORT LOGO <i>na</i>			\$30.00
	BOOTLID APPS LOGO <i>na</i>			\$40.00
	BOOTLID COMFORT TEL.NO LOGO <i>na</i>			\$30.00
				\$380.00
	Labour Charge			
	PANEL BEATING			\$25 \$600.00
	SPRAY PAINT			500 \$600.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
				40
	TOTAL LABOUR			\$1,250.00
	ESTIMATE TOTAL			\$2,952.44

Resu
Hp 90010068
3 days
P/P
19/04/23 @ 1100
Resy before
paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ARC Repair TP(CLSO)1 **JOB CARD** Sales Order: 5893575 JC NO305551547


CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO: SHB6388L	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 19.04.2023 08:05
	YR OF MANU: 28.10.2021	TARGET DATE
	CHASSIS CODE: KMHC851CVLU194945	COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 19.04.2023
 Nature: 3P.19.04.23

NO LABOR CODE DESCRIPTION



REMOVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Edge of Slip

Exit Pass

Vehicle No.: **SHB6388L** **JU INCOME**

Vehicle No.: **SHB6388L**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 821R

Vehicle Details

Vehicle No.: SHB6388L

Vehicle to be Exported: No

Intended Deregistration Date: 24 Apr 2023

Vehicle Make: HYUNDAI

Vehicle Model: AE IONIQ HEV FL 1.6 DCT

Primary Colour: Blue

Manufacturing Year: 2019

Engine No.: GALEKU431123

Chassis No.: KMHC851CVLU194945

Maximum Power Output: 103.6 kW (138 bhp)

Open Market Value: \$25,230.00

Original Registration Date: 28 Oct 2021

First Registration Date: 28 Oct 2021

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Oct 2029

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 27 Oct 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$37,186.00

COE Rebate Amount: \$30,251.00

Total Rebate Amount: \$34,001.00