

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305551547  
Date 19.04.23

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr RASUL  
Vehicle Reg No. SHB6388L Date of Accident : 19.04.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to : INCOME --- SMK359S
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	<u>\$1,710.50</u>
(b) Labour Charges	<u>\$1,065.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$2,775.50</u></b>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
<b>Final Lumpsum Repair cost</b>	_____

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature : \_\_\_\_\_  
Name : RASUL  
Date : \_\_\_\_\_

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_



COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305551547  
 REGN NO : SHB6388L  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 28.10.2021  
 DATE/TIME IN : 19.04.2023 08:05  
 ACCIDENT DATE : 19.04.2023

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00
0005	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	10.00	27.00
0006	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	10.00	27.00
0007	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44
0008	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04
0009	28-01-9999-2034-A	ZIG BOOK NOW APP LOGO REA	1 N	40.00	10.00	36.00
0010	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	55.00	10.00	49.50
0011	04-01-0104-3819-G	STAY-RR BUMPER LH	1	138.10	20.00	110.48
0012	04-01-0104-3919-G	STAY-RR BUMPER RH	1	138.10	20.00	110.48
0013	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305551547  
 REGN NO : SHB6388L  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 28.10.2021  
 DATE/TIME IN : 19.04.2023 08:0  
 ACCIDENT DATE : 19.04.2023

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 09-01-0104-2133-G ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40	
0015 04-01-0104-2370-G LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	
SUB-TOTAL :					1,710.50

## JOB NATURE

0000 L	PANEL BEAT (SHB6388L)TP	525.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 L	REMOVE/REFIX REVERSE SENSOR	40.00
SUB-TOTAL :		1,065.00
TOTAL :		2,775.50

\_\_\_\_\_  
 MVA NAME & SIGNATURE  
 DATE :

\_\_\_\_\_  
 SURVEYOR NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO