Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

REF: LPC1

ASS. REC. BY:

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

CO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s ICICHIN

of 617N

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: $65K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 32 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YP 5835U Yr Regn: 02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (01)

Make: Mit Canter c.c 2998

Colour White A/C: Insured / Std / Nil / NA

Sp.Reading — T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: FEB71EA-20379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/75R17.5

R: _____ (01)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal.	8 mm	R/Bal.	5 5 mm
L/Bal.	8 mm	L/Bal.	5 5 mm
D.O.A.	20/4/23	D.O.I.	25/4/2023

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

& RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: ___ $ + RS. ___ SI

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Parking

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($ _____)

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Not Authorised
L/Rep &
Recovery After Paint
32 days

金興(盤)汽車私人有限公司
K. KIM HING AUTO PTE LTD
160 Sungei Kadut Avenue #02-18/19/20
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32894

Vehicle Insured : YP 1626 H
Accident Date : 20-Apr-2023

Date : 24-Apr-2023

Our Ref : 023223 (LONPAC) / SANDRA

PAGE : 1

LANDSCAPE ENGINEERING PTE LTD
Singapore

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER (2998CC) (2017) YP5835U

1 pc	front cabin assy (used)		Rp 14,000.00 c
1 pc	air con condenser	]	Rp 3,000.00 c
1 pc	air con pipes	]	
1 pc	air con dryers	]	
1 pc	air con fan assy	]	
1 pc	air con fan assy bracket	]	
1 pc	air con cooling coil	]	
1 pc	air con blower	]	
1 pc	air con heater unit	]	
1 pc	engine mounting (1 set)	]	Dij 200.00 c
1 pc	gearbox mounting (1 set)	]	
1 pc	radiator assy	]	1,800.00 c ?
1 pc	radiator fan assy	]	
1 pc	radiator fan cowling	]	
1 pc	radiator fan blade	]	
1 pc	radiator fan clutch	]	
1 pc	air cleaner box assy	]	Rel 750.00 c
1 pc	air intake duct	]	
1 pc	turbo cooler		1,200.00 c ?
2 pcs	taillamp assy (LH/RH)	@ S$100.00	200.00 c
1 pc	dashboard meter		850.00 c ?
1 pc	front cabin mountings (2 pcs)		Rp 2,800.00 c
1 pc	front cabin mountings bracket (2 pcs)	]	
1 pc	rear cabin mountings (2pcs)	]	
1 pc	front cabin tilt shaft	]	
1 pc	front cabin tilt inner shaft	]	

	24,800.00	
Add 15% :	3,720.00	
		28,520.00

Con't Page 2 ...

12, 14

y key to continue...

金興(襲)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming Auto City
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : YP 1626 H
Our Ref : 023223

No. : 32894

6 pcs 'U' bolt (for securing wooden deck)	@ S$ 25.00	150.00 sn
1 pc rear wooden cargo deck assy		9,500.00 sn
2 pcs rear wooden chassis member	@ S$400.00	800.00 sn
1 pc rear canopy (sliding type with railing)		6,000.00 sn
1 pc rear lower step panel		400.00 sn
1 pc rear lower reinforcement		650.00 sn
1 pc reverse camera		550.00 sn
1 pc reverse sensor		220.00 sn
1 pc rear mudguard (2 pcs)]		450.00 sn
1 pc rear mudguard bracket (8 pcs)]		
2 pcs front & rear number plates	@ S$ 40.00	80.00 sn
1 pc radio headset		400.00 sn
1 pc ERP bracket		26.00 sn
2 pcs '60kmlh' & '23 pax' sticker	@ S$ 15.00	30.00 sn
1 pc company advertisement sticker		950.00 sn
To tow accident vehicle to workshop by normal towing		100.00
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		3,500.00
To remove aircon condenser, pipes and driers. Vaccum and recharge gas		100.00
To remove door's fittings		160.00 X
To remove and renew front wind-screen glass and conduct water leak test.		100.00 X
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.		280.00

Con't Page 3 ...

金興(龔)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-
Sin Ming Auto
Singapore 575
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : YP 1626 H
Our Ref : 023223

Page : 3
No. : 32894

To remove and refit front seat assy trim board and carpet to facilitate repairing works	nil 120.00 X
To check and realignment on chassis member.	1500 1,800.00
To putty and respray on affected portions.	1500 2,500.00
To focus Headlamps and Taillamps.	
To check front and rear lighting operation and rewiring	80.00 40
Remove and replace rear wooden deck in order to facilitate repairing works	1800 2,400.00
Total :	S$59,866.00

Singapore Dollars FIFTY NINE THOUSAND EIGHT HUNDRED AND SIXTY SIX Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) s[illegible]owed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SK0J234L0005 / K. KIM HIN AUTO PTE LTD
ENTRY DATE & TIME: 21/04/2023 21:42 (SGT)
SUBMITTED BY: Sandra Khong
VERSION: 1 (21/04/2023 21:42 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE
1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/04/2023 21:42 (SGT)
Reported by	Actual Driver
Date of Accident	20/04/2023 16:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	AYE to city near Clementi Ave 6
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP5835U

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Landscape Engineering Pte Ltd
Company Reg No	1XXXXX617N
Email Address	landscape@singnet.com.sg
Mobile Phone No	(Phone) +65-96607023
Alternative Phone No	(Office) +65-68832216

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Canter
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	0

INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Policy Number / Cover Note Number	Z23VC06114093

DRIVER

Name of Driver	Chandran Satheeshkumar
Passport No/FIN	GXXXX054M
Date Of Birth	20/05/1989
Occupation	Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

21/4

K Rajiv 21-06-2023

Policyholder's Signature / Date & Time

A. Satheesh Kumar

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

9:30

K. KIM HIN AUTO

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



› Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	617N

Vehicle Details

Vehicle No.:	YP5835U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Apr 2023
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB71ER4SDEC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C43747
Chassis No.:	FEB71EA20379
Maximum Power Output:	-
Open Market Value:	$37,955.00
Original Registration Date:	23 Feb 2017
First Registration Date:	23 Feb 2017
Transfer Count:	0
Actual ARF Paid:	$1,898.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	$48,901.00
COE Rebate Amount:	$18,750.00
Total Rebate Amount:	**$18,750.00**

he information contained herein is correct as at 24 Apr 2023

OK