

ASS. REC. BY:

REF:

072/ 23 0042 711/ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YQ 1598A

Yr Regn:

10.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU NNR85

c.c

2999

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

193105

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JAA NNR 85 H/C 7100397

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/85R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

77

mm

L/Bal.

9

mm

L/Bal.

77

mm

D.O.A.

20/4/23

D.O.I.

25/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 PM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/5 11 PM @ Mod Centre

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

F. 1/25

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06812

Vehicle Insured : GBJ5775M
Accident Date : 20-Apr-2023

Date : 24-Apr-2023

Our Ref : 023086 (CHINA) / CHAN

PAGE : 1

SINGAPORE ENGINEERING SERVICES PTE LTD
32 ANG MO KIO IND PARK 2
#05-03
SING INDUSTRIAL COMPLEX
Singapore 569510

Not Notarized
L1 Rmp B
Assembly After Paint
4 days

ESTIMATED COST OF REPAIR FOR ISUZU NNR85UH4A YQ1598A

1 pc O/s door
1 pc O/s door rubber
2 pcs O/s door hinge @ S\$ 77.00
1 pc O/s door channel
1 pc O/s door signal lamp
1 pc O/s door protector
1 pc O/s door arch garnish
1 pc O/s door mirror
1 pc O/s door mirror bracket
1 pc O/s corner panel
1 pc O/s door bracket top cover
1 pc O/s signal lamp
1 pc O/s headlamp
1 pc O/s headlamp lower garnish
1 pc Front grille (chrome)

By 882.00 ✓
Sn 160.00 ✗
N 154.00 ✗
N 77.00 ✓
By 92.00 ✓
N 59.10 ✓
N 86.00 ✓
CM 56.00 ✓
By 248.00 ✓
CM 220.00 ✓
N 29.00 ✓
CM 99.00 ✓
N 305.00 ✓
N 20.00 ✓
Sn 408.00 ✗

2,895.10
Less 15% : 434.27

2,460.83
N 100.00 sn ✓
500.00 *400*
600.00 *400*

1 pc O/s door lettering

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ5775M

Page : 2

Surge headlamp & check wiring
~~To lift up and tow vehicle to~~
~~workshop~~

20.00 ✓

Total : S\$ 3,680.83
=====

Singapore Dollars Three Thousand Six Hundred
and Eighty and Cents Eighty Three Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	393C

Vehicle Details

Vehicle No.:	YQ1598A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Apr 2023
Vehicle Make:	ISUZU
Vehicle Model:	NNR85UH4A
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	4JJ14E9347
Chassis No.:	JAANNR85HK7100397
Maximum Power Output:	-
Open Market Value:	\$35,241.00
Original Registration Date:	31 Oct 2019
First Registration Date:	31 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$1,763.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Oct 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,509.00
COE Rebate Amount:	\$17,266.00
Total Rebate Amount:	\$17,266.00

The information contained herein is correct as at 24 Apr 2023

OK