SHARON CHIONG



MOTOR SURVEY ASSIGNMENT

Date 26/04/2023 **Our Ref No.** D23001387MFQC

Accident Date 21-04-2023 Claim Type Own Damage

Insured Vehicle SLB807L Third Party Vehicle SLB807L

Survey Location CHENG HOE MOTOR PTE LTD Contact Person

BLK 1019 YISHUN IND. PARK A

#01-374/382 (S) 768761

Contact No. 67556142 **Fax No.** 67557719

Survey Type Revert for instructions

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person Fax No. 68416315

Contact Number 62563561

EXCESS APPLICATION FOR OWN DAMAGE CLAIM ADDITIONAL \$500.00 FOR INSURED VEHICLE INSTALLED WITH CNG TANKER

Basic	Y/I Driver	Total
\$500	\$0	\$500

Encl. Accident Reports & Estimate

Cc: Workshop CHENG HOE MOTOR PTE LTD Attention SHARON CHIONG

Officer Incharge ERICWOO

IMPORTANT NOTE

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.