

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4230h

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMP8376A Yr Regn: 2018, May

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Alfa Romeo Giulio c.c. 2891Colour: Red A/C: Insured / Std / NI / NASp. Reading: 37407 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZAREAEHV2J7586779Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 285 / 30 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 28/4/23Survey held at 4reusic UstkeDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.K. /

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ \$

Photos

Others

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 200B

### Vehicle Details

Vehicle No.: SMP8376A  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 25 Apr 2023  
Vehicle Make: ALFA ROMEO  
Vehicle Model: GIULIA 2.9 V6  
Primary Colour: Red  
Manufacturing Year: 2018  
Engine No.: 0008802  
Chassis No.: ZAREAEHV2J7586229  
Maximum Power Output: 375.0 kW (502 bhp)  
Open Market Value: \$85,459.00  
Original Registration Date: 23 May 2018  
First Registration Date: 23 May 2018  
Transfer Count: 3  
Actual ARF Paid: \$125,827.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 22 May 2028  
PARF Rebate Amount: \$94,370.00

### Intended COE Rebate Details

COE Expiry Date: 22 May 2028  
COE Category: E - Open - all except motorcycle  
COE Period(Years): 10  
QP Paid: \$38,039.00  
COE Rebate Amount: \$19,077.00  
**Total Rebate Amount: \$113,447.00**

The information contained herein is correct as at 25 Apr 2023

OK