

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: **GBJ 9339M**
 Policy No. **DMCVSNA00012212301**
 Claims No. **SNM23D202942/C02/TAYHP**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: 6786209 Yr Regn: 2017, May
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan Cabstar c.c. 2953
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 215570 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JNI SC2F7472859396
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/175
 R: 165/163 (D)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 20/4/2023 D.O.I. 28/4/23
 Survey held at MCR Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9490
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
26/5/23	Lump Sum \$4550 confirmed by email (Red 29,947.82,86%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) _____
 Date/Time, File Return to?
 2) 26/5/23-typist

Report Format: Merimen
 Lump Sum / L.S.: \$ 4550

Days Of Repair: 5
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 \$ + RS. _____
 Photos _____
 Others _____
 TOTAL _____

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : GBG 20G
 Made : Nissan
 Model : Cabstar 3.0
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate	1	\$ 1,688.40	\$ <i>bt</i> 1,688.40
2	Rear Tailgate "Nissan" Sticker	1	\$ 254.90	\$ <i>net</i> 254.90
3	Rear Tailgate Hinge Centre	1	\$ 92.50	\$ <i>net</i> 92.50
4	Rear Tailgate Hinge RH	1	\$ 92.50	\$ X 92.50
5	Rear Tailgate Hinge LH	1	\$ 92.50	\$ X 92.50
6	Rear Tailgate Side Latch RH	1	\$ 166.35	\$ X 166.35
7	Rear Tailgate Side Latch LH	1	\$ 166.35	\$ <i>bt</i> 166.35
8	Rear Tailgate Stopper Bracket RH	1	\$ 197.60	\$ X 197.60
9	Rear Tailgate Stopper Bracket LH	1	\$ 197.60	\$ X 197.60
10	Rear Tailgate Stopper Rubber RH	2	\$ 43.80	\$ X 87.60
11	Rear Tailgate Stopper Rubber LH	2	\$ 43.80	\$ X 87.60
12	Rear Tailgate Lower Panel (End Panel)	1	\$ 625.00	\$ <i>RY</i> 625.00
13	Rear Taillamp Assembly RH	1	\$ 311.40	\$ <i>CR</i> 311.40
14	Rear Taillamp Panel RH	1	\$ 227.50	\$ X 227.50
15	Rear Taillamp Assembly LH	1	\$ 311.40	\$ <i>CR</i> 311.40
16	Rear Taillamp Panel LH	1	\$ 227.50	\$ <i>RY</i> 227.50
17	Rear Number Plate Bracket	1	\$ 243.80	\$ ✓ 243.80
18	Rear Number Plate Lamp	1	\$ 114.30	\$ X 114.30
19	Spare Tyre Carrier	1	\$ 357.50	\$ X 357.50
20	Rear Exhaust Pipe	1	\$ 753.80	\$ X 753.80
21	Rear Exhaust Bracket	1	\$ 64.30	\$ X 64.30
22	Rear Side Gate RH	1	\$ 1,887.20	\$ X 1,887.20
23	Rear Side Gate LH	1	\$ 1,887.20	\$ <i>bt</i> 1,887.20
24	Rear Side Gate Lower Panel RH	1	\$ 799.00	\$ X 799.00
25	Rear Side Gate Lower Panel LH	1	\$ 799.00	\$ ✓ 799.00
26	Rear Mudguard RH	1	\$ 316.50	\$ X 316.50
27	Rear Mudguard LH	1	\$ 316.50	\$ X 316.50
28	Rear Chassis Crossmember	1	\$ 854.00	\$ X 854.00
Parts Sub Total :				\$ 13,219.80
10% Discount				\$ 1,321.98
PARTS TOTAL :				\$ 11,897.82

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ 30 hfr 50.00
2	Rear Reverse Sensor	1	\$ 250.00	\$ 200 nwr 250.00
3	Rear Reverse Camera	1	\$ 500.00	\$ x 500.00
4	Rear Tailgate "70km/h" Sticker	1	\$ 50.00	\$ nhr 50.00
5	Rear Tailgate "13 Pax" Sticker	1	\$ 50.00	\$ nhr 50.00
6	Rear Tailgate Aluminium Plate	1	\$ 1,200.00	\$ x 1,200.00
7	Rear Side Gate Top Stainless Steel Railing RH	1	\$ 1,500.00	\$ x 1,500.00
8	Rear Side Gate Top Stainless Steel Railing LH	1	\$ 1,500.00	\$ x 1,500.00
9	Rear Side Gate Aluminium Plate RH	1	\$ 1,800.00	\$ x 1,800.00
10	Rear Side Gate Aluminium Plate LH	1	\$ 1,800.00	\$ x 1,800.00
11	Rear Floor Panel Aluminium Plate	1	\$ 3,000.00	\$ x 3,000.00
12	Rear Canopy	1	\$ 3,500.00	\$ x 3,500.00
13	Rear Step Bracket	1	\$ 800.00	\$ hfr 800.00
14	Rear Tailgate Lower Panel (End Panel) Sealant	1	\$ 150.00	\$ x 150.00
15	Rear Sidegate Sealant RH	1	\$ 150.00	\$ x 150.00
16	Rear Sidegate Sealant LH	1	\$ 150.00	\$ x 150.00
17	Rear Tailgate Sealant	1	\$ 150.00	\$ x 150.00
SPECIAL NETT TOTAL :				\$ 16,600.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 600 1,800.00
2	To Spray Paint Affected Areas	\$ 700 1,600.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Rear Reverse Sensor	\$ 30 150.00
5	To Remove & Refix Rear Camera	\$ x 150.00
6	To apply anti rust on affected parts	\$ 40 120.00
7	To Conduct Water Leak Test	\$ x 100.00
8	To Remove & Refix Rear Exhaust Pipe	\$ x 150.00
9	To Remove & Refix Rear Floor Aluminium Plate	\$ x 300.00
10	To Remove & Refix Rear Tailgate Aluminium Plate	\$ x 200.00
11	To Remove & Refix Both Rear Side Gate Aluminium Plate	\$ x 400.00
12	To Remove & Refix Rear Canopy to facilitate repairs	\$ x 450.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ x 480.00
LABOUR TOTAL :		\$ 6,000.00

PARTS TOTAL : \$ 11,897.82

SPECIAL NETT TOTAL : \$ 16,600.00

LABOUR TOTAL : \$ 6,000.00

GRAND TOTAL : \$ 34,497.82

Tanpin 97445744
 wp 28/4/23 @ 230pm
 E/s Momy After repair
 Tanpin @ Ipoh town
 5 days
 - To check consistency of accident
 - To check part prices

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 248Z

Vehicle Details

Vehicle No.: GBG20G
Vehicle to be Exported: Yes
Intended Deregistration Date: 20 Apr 2023
Vehicle Make: NISSAN
Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: ZD30016747N
Chassis No.: JN1SC2F24Z0859396
Maximum Power Output: -
Open Market Value: \$25,665.00
Original Registration Date: 19 May 2017
First Registration Date: 19 May 2017
Transfer Count: 0
Actual ARF Paid: \$1,284.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 May 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$26,029.00
COE Rebate Amount: \$10,609.00
Total Rebate Amount: \$10,609.00

The information contained herein is correct as at 20 Apr 2023

OK

VEHICLE NO: G84 206

MAKE & MODEL: Nissan Cabstar

AUTO / MANUAL

DATE OF ACCIDENT	20 / 4 / 2023	CC 2500
TIME OF ACCIDENT	8.40 <u>AM</u> / PM	
LOCATION OF ACCIDENT	Along Hougang Ave 8	
EXACT PURPOSE USED AT TIME OF ACCIDENT	<u>EMPLOYMENT</u> / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER	SH Integrated Services PTE LTD	
EMAIL	Edwin@sh-integrated.com	OFFICE: MOBILE: 8418 6161
NRIC	200516248Z	
CLAIM TYPE	OD / <u>THIRTY PARTY</u> / REPORTING ONLY	
FLEET POLICY	YES / <u>NO</u>	
INCURANCE CO.	Ntuc	
TYPE OF COVERAGE	<u>Comprehensive</u> / Third Party / Third Party Fire & Theft	
POLICY NO.	5127364340	
NAME OF DRIVER	AS ABOVE / IF <u>NO</u> : Sarker Mohasin	
NRIC	G2087684R	
DATE OF BIRTH	12 / 07 / 1989	
ANY PASSENGER	<u>YES</u> / NO: 6	
NAME OF PASSENGER		
GENDER OF PASSENGER	<u>MALE</u> / FEMALE	
OCCUPATION	<u>Outdoor</u> / Indoor	
DATE OF DRIVING PASS	01 / 03 / 2018	
GENDER	<u>MALE</u> / FEMALE	
CONTACT NO.	Mobile: 82899706 Office: Home:	
EMAIL	EDWIN@SH-INTEGRATED.COM	
ADDRESS	Blk 25 Kak. Bukit Road 3 (E) 415815 #05-23	
DOES DRIVER OWN OTHER VEHICLES?	<u>NO</u> / If yes, Reg No: INSURE:	
RELATIONSHIP	<u>Employee</u> / If No:	
WEATHER CONDITION	<u>Sun</u> / Raining / Other:	
ROAD SURFACE	<u>Dry</u> / Wet / Other:	
ANY INJURIES	No / If yes / Who?	
CONTACT NO.		
POLICE REPORT	No / <u>Yes</u> , Where?	
NOTICE OF INTENDED PROSECUTION?	<u>NO</u> / If yes, Who?	
VEHICLE B NO.	G8J 9339M	Any Passenger: 0 0
NAME		
CONTACT NO.		
VEHICLE C NO.		Any Passenger:
VEHICLE D NO.		Any Passenger:
VEHICLE E NO.		Any Passenger:
VEHICLE F NO.		Any Passenger:
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / <u>NO</u>	
WAS THERE ANY AUDIO RECORDED?	YES / <u>NO</u>	
SCENE ACCIDENT PHOTOS TAKEN?	<u>YES</u> / NO	
WHO IS REPORTING	<u>DRIVER</u> / OWNER / BOTH	
Original Language Used	<u>English</u> / Mandarin / Others:	
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / <u>NO</u>	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

MOHASIN
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

	<p> Veh A: GBJ 204r Veh B: GBJ 9331M</p>
--	---

Describe Circumstance of the Accident

Refer to Police Report NO : T/20230420/2051

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

MOHASIN

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20230420/2051

1 of 4

Report No. T/20230420/2051

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/04/2023 14:22	Vide Report No.:	Station Diary No.: 66
--	------------------	--------------------------

Informant's Particulars

Name of Informant: SARKER MOHASIN		Address:	
ID Type / ID No.: FIN NO / G2087684R		Contact No.: Home/Office:	Mobile: 82899706
Nationality: BANGLADESHI		Email:	
Sex: Male	Age: 33	Date of Birth: 12/07/1989	Type of Informant: Driver
Race: Bangladeshi		Language: English	
Occupation: Lorry driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/04/2023 08:45	Type of Location: Straight Road
Location: HOUGANG AVENUE 8				
Lamp Post Number: 50				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG20G	Lorry				Slightly Damaged	5
GBJ9339M	Van					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20230420/2051

2 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No: T/20230420/2051

CONTINUATION OF REPORT

Passenger			
Name	Islam Ariful	ID No.	G2115863T
Related Vehicle	GBG20G (Lorry)	Contact No.	82653543
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	Mian Sani	ID No.	G8594452K
Related Vehicle	GBG20G (Lorry)	Contact No.	97786579
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	SARKER MOHASIN	ID No.	G2087684R
Related Vehicle	GBG20G (Lorry)	Contact No.	82899706
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	Don	ID No.	F8469232T
Related Vehicle	GBG20G (Lorry)	Contact No.	81793769
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight



Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Passenger			
Name	Zahir	ID No.	F7882841L
Related Vehicle	GBG20G (Lorry)	Contact No.	98604161
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	Hossain Mannan	ID No.	G2645456K
Related Vehicle	GBG20G (Lorry)	Contact No.	88378177
Hospital/Clinic	LIFEPLUS GROUP	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/04/2023	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 20/04/2023 at about 0845hrs, I was driving my company's lorry (GBG20G) along Hougang Ave 8 near Monfort Secondary School near Lamp post 50. The traffic light had turned red and I have stopped my vehicle and suddenly a vehicle (GBJ9339M) hit my vehicle from the rear.

After the collision, I came out of my vehicle to make a check on my passengers. I am a driver for SH Integrated Services PTE LTD and had 5 passengers with me at the time, 2 in front and 3 at the carrier of the lorry. The passengers were from a different company, DRC Engineering PTE LTD and I was sending them to Maris Stella Secondary School. They informed that they were all suffering from pain due to the collision.

I then checked on my vehicle and it had sustained some damages. The rear left taillight was damaged and the door to the back carrier was damaged as it could not open. I then informed the driver of GBJ9339M that was had to report the matter to my company as the vehicle belongs to them. We then exchanged particulars and left the scene. The driver of GBJ9339M was Huang Xingwang, Douglas, NRIC: S8335662F, DOB: 07/11/1983, HP: 96224147.

I had called my supervisor regarding the matter, they had instructed to get a medical check and make a police report. I then proceeded to LifePlus Medical Group (Hougang Central) and 3 days of MC. 5 other passengers that was with me at the time was given 3 days of MC as well.

I further wish to inform that my company's lorry had an in-car camera at the front and was operational at the time of the incident.



**SINGAPORE
POLICE FORCE**



T/20230420/2051

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

4 of 4

Report No. T/20230420/2051

CONTINUATION OF REPORT

Signature of Officer Recording The Report: F / SGT 1 JARED NG	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / AEIT / SI TAN JEOK LENG LESLIE Contact No.: 65476151	

Signature Of Informant:	
Date/Time: 20/04/2023 14:22	
Classification Of Case:	

NP168