

ASS. REC. BY:

REF:

EGZ/23 004325/KV

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMPG23001918

Claims No. CDMPG23001002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Damaged doesn't look like park & pound, likely hit onto railing.  
See whether insurance needs investigation??

20/6 @ 5601.10 Car (red 1165.10, 17%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/6/23-typist

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 5601.10)

investigation- \$500

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	029H
<b>Vehicle Details</b>	
Vehicle No.:	SND8430C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Apr 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	CN7 AVANTE 1.6 DOHC CVT S
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	G4FMMU107786
Chassis No.:	KMHLN41ETNU258956
Maximum Power Output:	90.2 kW (120 bhp)
Open Market Value:	\$18,746.00
Original Registration Date:	27 Jan 2022
First Registration Date:	27 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2032
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Jan 2032
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,898.00
COE Rebate Amount:	\$46,318.00
<b>Total Rebate Amount:</b>	<b>\$50,068.00</b>

The information contained herein is correct as at 26 Apr 2023

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	25/04/2023 13:55 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	25/04/2023 11:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	DEPOT LANE LOT 80 TO 85
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND8430C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KEE MENG SUAN
NRIC No	SXXXX029H
Email Address	meng.suan@live.com
Mobile Phone No	(Phone) +65-85330055
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1600

### INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG23001918

### DRIVER

Name of Driver	KEE MENG SUAN
NRIC No	SXXXX029H
Date Of Birth	25/10/1992
Occupation	Outdoor

Date Of Driving Pass	14/02/2013
Driving experience	10 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-85330055
Alt. Phone Number	-
Email Address	meng.suan@live.com
Address	BLK 12 TECK WHYE LANE #09-838
Address complement	-
Postcode	680122
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong Division Headquarters
Police Station Phone No	(Phone) +65-18007910000
Alt. Police Station Phone No	(Fax) +65-68965647
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

## Sketch Plan

Depot Lane Car Park (Lot 80-85)





# SINGAPORE POLICE FORCE



J/20230425/7027

1 of 2

**POLICE REPORT (NP299)**

Report No. J/20230425/7027

Police Station Of Origin  
Jurong Division HQ  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No:1800-7910000

Date/Time Report Made 25/04/2023 11:34	Vide Report No.	Station Diary No.		
Name Of Informant KEE MENG SUAN	Address 122 TECK WHYE LANE #09-838 SINGAPORE 680122			
ID Type / ID No. NRIC NO / S9240029H	Contact No. Home/Office:	Mobile: 85330055		
Nationality SINGAPORE CITIZEN	Email Address MENG.SUAN@LIVE.COM			
Occupation Supply and distribution/Logistics/Warehousing manager	Sex Male	Age 30	Date of Birth 25/10/1992	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 25/04/2023 09:00 - 25/04/2023 11:30	Location Of Incident 122 TECK WHYE LANE #09-838 SINGAPORE 680122			

**Brief details.**

My vehicle SND8430C polar white hyundai Avante was involved in a hit and run incident. Happend during 25/04/2023 9am to 11.30am at depot lane season parking lot 80 to 85. I came to withdraw my working vehicle and parked my Avante at the season parking lot. After coming back to depot lane to Alex change vehicle, I found out that my front bumper, mud guard and door are damaged. There's no witness after asking the working staff near to this parking lot.my vehicle do not have a 24hrs recording and couldn't capture any footage after the vehicle was off.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 25/04/2023 11:34
Officer In-Charge Of Case:	Classification Of Case:





**SINGAPORE  
POLICE FORCE**



J/20230425/7027

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20230425/7027

Subjects Involved			
Victim			
Person Name	KEE MENG SUAN		
ID Type	NRIC NO	ID No	S9240029H
Gender	Male	Age	30
Race	Chinese	Language	English
Occupation	Supply and distribution/Logistics/Warehousing manager	Address	122 TECK WHYE LANE #09-838 SINGAPORE 680122
Mobile No	85330055	Is Informant A Victim?	Yes
Person Name	KEE MENG SUAN (Informant)		

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
25/04/2023 11:34

Classification Of Case:





FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD  
CO. REG. No.: 1995-01140-D

INSURER: ERGO Insurance Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG23001918	Date of Loss:	25/04/2023
Vehicle Reg. No.:	SND8430C	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEE MENG SUAN	Contact No:	+6585330055
Driver:	KEE MENG SUAN		
Make/Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Vehicle Reg. Date:	27/01/2022
Vehicle Colour:	PEARL WHITE		
Engine No:	G4FMMU107786	Chassis No:	KMHLN41ETNU258956
Odometer:	43504 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	X 6 day		
Remarks:	KINDLY ARRANGE OD CLAIM SURVEY. VEHICLE IN OUR SIN MING WORKSHOP		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

*Not Authorised  
Return By claim  
Ex \$500*

**COST OF CLAIMS**

	Amount
Parts	3,415.40
Miscellaneous Items	0.00
Labour	3,320.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>6,735.40</b>
<b>+ GST 7.00% (\$\$)</b>	<b>471.48</b>
<b>Nett Amount (\$\$)</b>	<b>7,206.88</b>

This claim is handled by: ESPERANZA FERNANDO CAMUNGOL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 Apr 2023)  
**Parts:** 143      HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*285.00 F	✓
2	1		*FRONT BUMPER CLIPS	0	0.00	*60.00 FS	✓
3	1		*FRONT BUMPER LOGO	0.00	0.00	*35.00 F	✓
4	1		*FRONT RADIATOR GRILLE	0.00	0.00	*185.00 F	✓
5	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*115.00 F	✓
6	1		*FRONT BUMPER AIRDUCT 20	0.00	0.00	*25.00 F	✓
7	1		*FRONT BUMPER TOP	0.00	0.00	*95.00 F	X
8	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	*28.00 F	✓
9	1		*RH HEADLAMP	0.00	0.00	*750.00 F	✓
10	1		*RH FRONT FENDER	0.00	0.00	*410.00 F	✓
11	1		*RH FRONT FENDER UNDERSHIELD	0.00	0.00	*65.00 F	✓
12	1		*RH FRONT FENDER UNDERSHIELD CLIPS	0	0.00	*40.00 FS	✓
13	1		*RH FRONT DOOR	0.00	0.00	*850.00 F	✓
14	1		*RH FRONT DOOR TOP HINGE	0.00	0.00	*38.00 F	X
15	1		*RH FRONT DOOR LOWER HINGE	0.00	0.00	*38.00 F	X
16	1		*RH FRONT DOOR GARNISH	0.00	0.00	*30.00 F	✓
17	1		*RH FRONT DOOR INNER SEAL	0.00	0.00	*65.00 F	X
						Sub Total (\$\$)	3,114.00
						+ Margin on L,N Items 10.00% (\$\$)	301.40
						Total Parts (\$\$)	3,415.40

F=Franchise part. S=SpcNett.

RH head lamp support

CM 28.00 ✓

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			201
1	TO FOCUS HEADLAMP/ CHECK LIGHT SYSTEM	New	50.00
2	COMPUTERISED WHEEL ALIGNMENT	New	601 120.00
3	TO TRANSFER FRONT DOOR PARTS	New	601 100.00
4	TO REPAIR/ RESPRAY RH FRONT SPORTS RIM	New	801 200.00
5	TO REPAIR BONNET , RH ROCKER PANEL, RH REAR DOOR , RH REAR FENDER, REAR BUMPER INCLUDES REPLACEMENT OF PARTS	New	6001 850.00
6	TO SPRAY PAINTING BONNET, FRONT BUMPER,FRONT BUMPER TOP, RH FRONT FENDER, RH FRONT DOOR,RH REAR DOOR, RH ROCKER PANEL,REAR BUMPER	New	16001 2,000.00
Gross Labour Cost (\$\$)			3,320.00

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: