

ASS. REC. BY:

REF: EG21

## ASSIGNMENT

Hennerth

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

Falcon

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

500k

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$124k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 06 days

Res.: Yes or No

Lum Sum: 1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SND 8430CYr Regn: 01, 22Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: HyundaiAvante

c.c.

1598Colour: White

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: 43504

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH LN41ETRU 258956Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD A/Rlm or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 25/4/23D.O.I. 27/4/2023

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Old car & old body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Damaged, doesn't look like park & found, likely hit onto railing.  
See whether insurance needs investigation??

Data/Time, File Pass to?



: Prel. Report

1)

Data/Time, File Return to?



: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RS - SI

Paints

Others

Add Fee: ☐

: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL



# FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD  
CO. REG. No.: 1995-01140-D

INSURER: ERGO Insurance Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG23001918	Date of Loss:	25/04/2023
Vehicle Reg. No.:	SND8430C	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEE MENG SUAN	Contact No:	+6585330055
Driver:	KEE MENG SUAN		

Make/Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Vehicle Reg. Date:	27/01/2022
Vehicle Colour:	PEARL WHITE		
Engine No:	G4FMMU107786	Chassis No:	KMHLN41ETNU258956
Odometer:	43504 KM		

Paint Type:  
Total Loss?  
Est. Duration of Repair (day)

NO

76 days

*Not Authorised  
Repairing Body  
Ex @ 500k*

Remarks: KINDLY ARRANGE OD CLAIM SURVEY. VEHICLE IN OUR SIN MING WORKSHOP  
Present Location: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)

## COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	3,415.40
Labour	0.00
Paintwork Labour	3,320.00
Towing	0.00
	0.00
<b>Gross Total (\$\$)</b>	<b>6,735.40</b>
<b>+ GST 7.00% (\$\$)</b>	<b>471.48</b>
<b>Nett Amount (\$\$)</b>	<b>7,206.88</b>

This claim is handled by: ESPERANZA FERNANDO CAMUNGOL

Generated using Merimen e-Claims Internet Estimation & Adjusting System



Estimates on Miscellaneous Items  
There are no new miscellaneous items selected.

## Estimates on Labour

No Particulars

		Lab.Type	Amount
<b>Labour Items</b>			
1	TO FOCUS HEADLAMP/ CHECK LIGHT SYSTEM		201
2	COMPUTERISED WHEEL ALIGNMENT	New	50.00
3	TO TRANSFER FRONT DOOR PARTS	New	601 120.00
4	TO REPAIR/ RESPRAY RH FRONT SPORTS RIM	New	601 100.00
5	TO REPAIR BONNET , RH ROCKER PANEL, RH REAR DOOR , RH REAR FENDER, REAR BUMPER INCLUDES REPLACEMENT OF PARTS	New	801 200.00
6	TO SPRAY PAINTING BONNET, FRONT BUMPER, FRONT BUMPER TOP, RH FRONT FENDER, RH FRONT DOOR, RH REAR DOOR, RH ROCKER PANEL, REAR BUMPER	New	601 850.00
		New	16001 2,000.00
Gross Labour Cost (\$\$)			3,320.00

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### FALCON-AIR AUTO SERVICES PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 - No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# REFERENCE

Part Source: MRM-SG  
 Parts: 143  
 Labour: Repairer's  
 Print Code: Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Version: 1.0 (Last Synchronised: 26 Apr 2023)  
 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)  
 (Price-denominated Standard List)

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*285.00 F	1
2	1		*FRONT BUMPER CLIPS	0	0.00	*60.00 FS	1
3	1		*FRONT BUMPER LOGO	0.00	0.00	*35.00 F	1
4	1		*FRONT RADIATOR GRILLE	0.00	0.00	*185.00 F	1
5	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*115.00 F	1
6	1		*FRONT BUMPER AIRDUCT	0.00	0.00	*25.00 F	1
7	1		*FRONT BUMPER TOP	0.00	0.00	*95.00 F	X
8	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	*28.00 F	1
9	1		*RH HEADLAMP	0.00	0.00	*750.00 F	1
10	1		*RH FRONT FENDER	0.00	0.00	*410.00 F	1
11	1		*RH FRONT FENDER UNDERSHIELD	0.00	0.00	*65.00 F	1
12	1		*RH FRONT FENDER UNDERSHIELD CLIPS	0	0.00	*40.00 FS	1
13	1		*RH FRONT DOOR	0.00	0.00	*850.00 F	1
14	1		*RH FRONT DOOR TOP HINGE	0.00	0.00	*38.00 F	1
15	1		*RH FRONT DOOR LOWER HINGE	0.00	0.00	*38.00 F	1
16	1		*RH FRONT DOOR GARNISH	0.00	0.00	*30.00 F	1
17	1		*RH FRONT DOOR INNER SEAL	0.00	0.00	*65.00 F	X

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,114.00
+ Margin on L,N Items 10.00% (\$\$)	301.40
<b>Total Parts (\$\$)</b>	<b>3,415.40</b>

Falcon-Air Auto Services Pte Ltd/SND8430C/26/04/2023 15:58. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	029H
Vehicle Details	
Vehicle No.:	SND8430C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Apr 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	CN7 AVANTE 1.6 DOHC CVT S
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	G4FMMU107786
Chassis No.:	KMHUN41ETNU258956
Maximum Power Output:	90.2 kW (120 bhp)
Open Market Value:	\$18,746.00
Original Registration Date:	27 Jan 2022
First Registration Date:	27 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2032
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2032
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$57,898.00
COE Rebate Amount:	\$46,318.00
Total Rebate Amount:	\$50,068.00

The information contained herein is correct as at 26 Apr 2023

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the G/A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission 25/04/2023 13:55 (SGT)  
Reported by Both Policyholder and Actual Driver  
Date of Accident 25/04/2023 11:30 (SGT)  
Exact Location of Accident Singapore  
Additional Location Information DEPOT LANE LOT 80 TO 85  
Country/State of Loss Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SND8430C

### INSURED/POLICYHOLDER

Is company? No  
Name Of Registered Owner KEE MENG SUAN  
NRIC No SXXXXX029H  
Email Address meng.suan@live.com  
Mobile Phone No (Phone) +65-85330055  
Alternative Phone No -

### VEHICLE PARTICULARS

Manufacturer Hyundai  
Model Avante  
Variant -  
Exact purpose for which vehicle was being used at time of Private use  
accident  
Are you claiming under your own insurance policy for repair to Yes  
your vehicle? Private car  
Vehicle Category 1600  
Transmission Auto  
CC

### INSURANCE COMPANY

Name of Insurance Company ERGO Insurance Pte. Ltd.  
Policy Number / Cover Note Number DMPG23001918

### DRIVER

Name of Driver KEE MENG SUAN  
NRIC No SXXXXX029H  
Date Of Birth 25/10/1992  
Occupation Outdoor



## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Sketch Plan

Depot Lane Car Park (Lot 80-85)



Damage  
Part





# SINGAPORE POLICE FORCE

## POLICE REPORT (NP299)

Police Station Of Origin  
Jurong Division HQ  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7910000



J/20230425/7027

1 of 2

Report No. J/20230425/7027

Date/Time Report Made 25/04/2023 11:34	Vide Report No.	Station Diary No.
Name Of Informant KEE MENG SUAN	Address 122 TECK WHYE LANE #09-838 SINGAPORE 680122	
ID Type / ID No. NRIC NO / S9240029H	Contact No. Home/Office:	Mobile: 85330055
Nationality SINGAPORE CITIZEN	Email Address MENG.SUAN@LIVE.COM	
Occupation Supply and distribution/Logistics/Warehousing manager	Sex Male	Age 30
Institution/School Name	Language English	Date of Birth 25/10/1992
Date/Time Of Incident 25/04/2023 09:00 - 25/04/2023 11:30	Location Of Incident 122 TECK WHYE LANE #09-838 SINGAPORE 680122	Race Chinese

### Brief details.

My vehicle SND8430C polar white hyundai Avante was involved in a hit and run incident. Happend during 25/04/2023 9am to 11.30am at depot lane season parking lot 80 to 85. I came to withdraw my working vehicle and parked my Avante at the season parking lot. After coming back to depot lane to Alex change vehicle, I found out that my front bumper, mud guard and door are damaged. There's no witness after asking the working staff near to this parking lot.my vehicle do not have a 24hrs recording and couldn't capture any footage after the vehicle was off.

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
25/04/2023 11:34

Classification Of Case: