



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD	Ref: NS/INC23004334/Swp3e2
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557	Date: 15-05-2023
	Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 6537L	Veh. Inspected	SHC 2234T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1218359-002	Excess (\$)	0.00
Assign From		Assign Date	17/04/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVJU103415	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MOZZO	6 mm
L/H Front Tyre	195/65 R15	MOZZO	6 mm
R/H Rear Tyre	195/65 R15	MOZZO	6 mm
L/H Rear Tyre	195/65 R15	MOZZO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/04/2023	Inspection Date	17/04/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------