

108/10E 1/3
ASS. RE. BY: [Signature]

REF: CS3/INR 23004340/RWY3

087K

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 43094

at Workshop m/s HUA CHIN MOTOR

of 50, BUKIT DATUK ST 23

Insured: SMR

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 6K

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBL 43094 Yr Regn: 2016 / OCT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CBF 190WH C.C. 184

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 2451 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LWBMC 48904/1104263

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-17

R: 150/70-17

BS / DJN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ZENOS

Front

R/Bal: 4 mm R/Bal: 4 mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A. 20/04/23 D.O.I. 27/04/23

Survey held at HUA CHIN

Des. of Damages: Front / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 3.5K

ESTIMATE RANGE OF REPAIR / no. of days - (2K-3K) / 3 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS _____ \$

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Foreign Identification Number

087K

Vehicle Details

Vehicle No.:

FBL4309Y

Vehicle to be Exported:

No

Intended Deregistration Date:

04 May 2023

Vehicle Make:

HONDA

Vehicle Model:

CBF190WH

Primary Colour:

Red

Manufacturing Year:

2016

Engine No.:

MC46E5014456

Chassis No.:

LWBMC4690H1104263

Maximum Power Output:

-

Open Market Value:

\$2,888.00

Original Registration Date:

17 Oct 2016

First Registration Date:

17 Oct 2016

Transfer Count:

4

Actual ARF Paid:

\$434.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

16 Oct 2026

COE Category:

D - Motorcycle

COE Period(Years):

10

QP Paid:

\$6,501.00

COE Rebate Amount:

\$2,242.00

Total Rebate Amount:

\$2,242.00