TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SKZ 3753 Z

Your ref:

SKD 8099 L

26 April 2023

HL ASSURANCE PTE. LTD.

11 KEPPEL ROAD #11-01 ABI PLAZA SINGAPORE 089057 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : LOH WEI VEHICLE NUMBER : SKZ 3753 Z

YOUR INSURED VEHICLE NUMBER: SKD 8099 L ACCIDENT ON 26 APR 2023 AT ABOUT 12:35 HOURS ALONG THE POIZ CENTRE S(347697) LEVEL 1 CARPARK

We refer to your email / fax dated **26 Apr 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

Twincar Automotive Pte Ltd