



Service Request Details

Claim

S3M04M0W

Reference

CS/HSB23004357/p3 

Loss Date

25 April 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

27 Apr 2023 9:51:04 AM

Request Date

27 April 2023

Due Date

27 April 2024

Services

Pre-Repair Survey

Actions

Next Step

Complete work

More ▼

Vehicle Information

Incident Vehicle Registration #
SKU5024H

Make
TPVD

Model
VOLKSWAGEN

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

