

Service Request Details

Claim	S3M04M0W
Reference	CS/HSB23004357/Awp3e2
Loss Date	25 April 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	27 Apr 2023 9:51:04 AM
Request Date	27 April 2023
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident	SKU5024H
Vehicle	
Registration #	
Make	TPVD
Model	VOLKSWAGEN

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

Claim Handler

OH Vale

vale.oh@axa.com.sg

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

Invoice

Surveyor/ Assessor expense

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2303112.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 May 2023
 SKU 5024H Preliminary advice.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2023
 SJ0G234Q001E-SH9293U.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	27 April 2023
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	27 April 2023
 PRI TP PDF.pdf.pdf	Legal	Others	KUMAR Shailendra	27 April 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	27 April 2023
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	27 April 2023