

ASS - RE BY

REF: CS/SPF 23004762/Rwy 3

562H

ASSIGNMENT

COE-2630/300

From: _____ Date: _____

Estimated Cost: _____

OD / TP/WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBE 3424 R

at Workshop no/s PETROL STATION

of 219, BUKIT TIMAH RD

Insured: SPF

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18k

IDAC Accident Report Consistent? : Yes or No.

GIA / PR Seen: Consistent? : Yes or No.

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBE 3424 R Yr Regn: 2010 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: DUCATI M1100 c.c. 1079

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 87 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 20MM502AA9B02778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: order / Jammed / Leaked / Burnt or

Brake: order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim. or

Tyre Size: F: 120/70 ZR17

R: 180/55 ZR17

BS / DJN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>5</u> mm
L/Bal. _____ mm	L/Bal. _____ mm

D.O.A. 25/04/23 D.O.I. 27/04/23

Survey held at 219, BUKIT TIMAH RD

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 15k

ESTIMATE RANGE OF REPAIR (NO. OF DAYS (1K-2K) / 3 days

Date/Time, File Pass to?

☐ : Prell. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. _____

Photos _____

Others _____

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

562H

Vehicle Details

Vehicle No.:

FBE3424R

Vehicle to be Exported:

No

Intended Deregistration Date:

03 May 2023

Vehicle Make:

DUCATI

Vehicle Model:

M1100

Primary Colour:

Red

Manufacturing Year:

2009

Engine No.:

ZDM1078AC006062

Chassis No.:

ZDMM502AA9B027778

Maximum Power Output:

*

Open Market Value:

\$13,732.00

Original Registration Date:

03 Mar 2010

First Registration Date:

03 Mar 2010

Transfer Count:

3

Actual ARF Paid:

\$2,060.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

*

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 Jan 2030

COE Category:

D - Motorcycle

COE Period(Years):

10

PQP Paid:

\$3,860.00

COE Rebate Amount:

\$2,652.00

Total Rebate Amount:

\$2,652.00