

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	Ref	: (	CS3/SMO23004366/Uny3m4		
	50 RAFFLES PLAC SINGAPORE LAND	Dat	e: (	09/05/2023		
			Cod	de: S	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBH 5224Y	Veh. Inspected	(	GBK 8421J	
	Policy No.		Coverage (\$)	(	0.00	
	Claim No.	CMTD2301652/AGC	Excess (\$)	(	0.00	
	Assign From	BETTY WONG	Assign Date	2	27/04/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ VIANO (A)	c.c	2	2143	
	Engine No.	HIDDEN	Year of Reg.	2	2012	
	Chassis No.	WDF63981523718054	Colour	I	BLACK	
	Odometer	197429 KM	Steering	I	IN ORDER	
	Brakes	IN ORDER	Modification	,	STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make	l	Balance	
	R/H Front Tyre	215/55 R17	MICHELIN	(	6 mm	
	L/H Front Tyre	215/55 R17	MICHELIN	6	6 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN	(	6 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN	6	6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	EHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
5.	General Information					
	Accident Date	20/04/2023	Inspect Date / Time	e (	02/05/2023 ( 12:30 PM )	
	Survey held at	2 KAKI BUKIT AVE 2 #01-11, AU	ITOHUB @ KAKI BUK	Т		
	Repairer	BEST AUTO K PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/SMO23004366/Uny3m4

Inspected By

**CHUA KANG SENG** Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**