

ASS. REG. BY: Sum.2 REF: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: INC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Valt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \$ _____
 IDAC Accident Report: _____ Consider 7: Yes or No
 GIA / PR Scen: _____ Consider 7: Yes or No
 Est. Repair: 3 days Rest: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: Sh9960C Yr Regr: 30/10/2019
 Type: MCar / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai / Lonix CC: 1580
 Colour: Blue AC: Insured / Std / NA
 Sp. Reading: 568719 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/Nr: KmhC851C1V188594
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD / R/Rim or
 Tyre Size: F: 195/65 R15
 R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LZA / M/C / OHTSU / PRI / SUMI /
 TOYO / YOKO or WBS710K1

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
U/Bal. <u>5</u> mm	U/Bal. <u>5</u> mm
D.O.A. <u>12/4/23</u>	D.O.A. <u>13/4/23</u>

Survey held at Comfort
 Des. of Damages: Fnt / Rear / O/S / A/S / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

1) _____
 Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / LBJ: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation

\$ + RS: \$ _____

Photos

Others

TOTAL

Date/Time: 13.04.2023 08:19

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5892869

JC NO305551023

CUSTOMER COMFORT TRANSPORTATION PTE LTD MS 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO: SH 9960C	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 12.04.2023 15:45
	YR OF MANU. 30.10.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU188594	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

LS
Income


PBQ
6199H

Ident Date: 12.04.2023
RE: 3P 12.04.2023/C

LABOR CODE
10 PB

LKK-

DESCRIPTION
LUMP SUM REPAIR-SH 9960C-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SH 9960C LIMITS

Vehicle No.: SH 9960C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard